Debbie Bailey 503-229-6811

USEPA SF
1636781

Magnum Salvage / Horizon Vehicles

Open access

PCBs
Metals
acids

→ Off-site migration to RV park

→ Not able to locate property owners?
→ Zumwalt
→ status on ownership / still in charge?

- Any burning?
- GW samples analyzed for metals?
- 1977 – no information on salvage operations
- Batteries on-site → salvage of batteries for lead plates?
- Did PP&L ever find anything in their records?

No

Transformer area 1/2 back on property along north side of yard.

W. well 200
RB 140
TB 150



Oregon National Guard

- Port of Portland contact: Russ Korvala (503) 231-5000, ext. 608
- ODEQ contact: Marlene Daniels (503) 229-6941
- Labs / QA: Laura Casstrelli (206) 442-4323
  - Inorganics → Laucks Testing Labs Inc (Ronda) 442-7121
    921 South Harney St.
    Seattle, WA. 98108
    (206) 767-5060
  - ~~Inorganics~~
    BNA
    Pesticides
    } Charlene Nixs
    EPA Laboratory Region X
    7411 Beach Drive, East
    Port Orchard, WA. 98366

    Contact: Peggy Jensen (206) 442-0370

EPA #s 8914 2000 - 2009
TEC 454A
9TFA10PUZZ
Storet #s

- VOC → TMA / NORCAL
  Case # 11712

2030 Wright Ave
Richmond, Calif 94804
(415) 235-2633
Attn: Jane Anderson

Summary: 2 on-site wells (2" PVC casing, 15' deep)
1 BKG Domestic well (Need to Find, Golf course)
EM31 survey / Possibly EM34 in anomalous areas

STORET #s
ONG
3 GW
FBD
5 GW
10 Sed.
Magnum
4 GW
3 Sed.

T15 R3W
Sec. 9, 8, 5, 10
6, 7, 4, 18, 17

Bill Rogers Honda 4120 Santiam Hwy
8'-32' water (screened 132-140

Blue Ox RV Park 119' water
121-131' (screened)

Church of Christ 2120 13-Lakes Rd
45' water - Screened 51-55'

(b) (6)

15' water well 32'

(b) (6)

42' water well 45'

(b) (6)

19' well 24'

clay w/sand
sand/gravel
clay/w sand
sand/gravel

V.F.W
29' water 34' well

South of site (next door)
1130 Gold Fish Farm Rd
22' water 53' well

(b) (6)

23' water 54' well

Eugene Shear Airport
21' water well 43'

(b) (6)

7' water well 30'

(b) (6)

23' water 104' well

(b) (6)

20' water 36' well