SDMS Document ID
1028588



Source: USGS Digital Orthophoto Quadrangle, 1998

N
S

0 65 130 260 390 520 Feet

Legend

- RAARTP1D1 — XRF Soil Sample Location and Sample ID
- RAARTP1D1 — XRF Soil Sample with Laboratory conformation

Analytical Results Report
TDD No. 0308-0013

Rico Argentine
Rico, Dolores County, Colorado
Residential Depth Soil Sample Location Map
Figure 5

January 2004