

Figure 2-5
Operable Unit 1
2007
Soil Investigation Results

Libby Asbestos Project
Libby, Montana

CDM

Document: R:\2603-Volpel\ProcessPlant\gis\mxd\Figure2-5_Contamination_Sampling_FieldGridDesc_11x17.mxd

1078894