12/8/15: McWane Ductile, Coshocton, OH

Arrived 9:45 AM

checked in at security
met w/ Eric Squire, Asst. Env. Manager

Mentioned inspection 3 weeks ago - Pat + David
raw mat. charging bucket - in scrap prep
overhang shroud area

cupola cap open at end of day - ~2:30-2:45 pm

tour 10:15 am

not running - issue w/something
started running 10:28 am - photo of cupola charge bucket ~~chute~~ shroud

10:30 am - charge bucket went up
took 2 photos of VEs coming from shroud
observed them escaping out to atm

Kristin - VEs coming out from actuator arm holes

Marie set up opacity camera
started at 11:00 AM

Finished 11:35 AM

Told about inspection report

Photos confidential

Finished at 11:40 AM