ANALYTICA
Environmental Laboratories

12189 Pennsylvania St.
Thornton, CO 80241
(303) 469-8868
Fax (303) 469-5254

SDMS Document ID
2007170

11/11/2002

MFG Environmental Incorporated
4900 Pearl East Circle
Suite 300W
Boulder, CO 80301
Attn: Dave Colvin

Work Order #: B0210219
Date: 11/11/2002
Work ID: VB/170
Date Received: 10/18/2002

Sample Identification

Lab Sample Number	Client Description	Lab Sample Number	Client Description
B0210219-01	3-90034-R	B0210219-02	3-90035-R
B0210219-03	3-90036-R	B0210219-04	3-90036-D
B0210219-05	3-90038-R	B0210219-06	3-90039-R
B0210219-07	3-90040-R	B0210219-08	3-90041-R
B0210219-09	3-90042-R	B0210219-10	3-90043-R
B0210219-11	3-90043-D	B0210219-12	3-90044-E
B0210219-13	3-90045-R	B0210219-14	3-90037-E
B0210219-15	V1612-W-CHP-2	B0210219-16	V1612-W-CHP-1
B0210219-17	V2191-W-CHP-1	B0210219-18	V2191-W-CHP-2

Enclosed are the analytical results for the submitted sample(s). Please review the CASE NARRATIVE for a discussion of any data and/or quality control issues. Listings of data qualifiers, analytical codes, key dates, and QC relationships are provided at the end of the report.

Sincerely,

Joe Egry
Project Manager

"The Science of Analysis, The Art of Service"