SITE INSPECTION REVIEW FORM

SITE NAME: Amenia

CITY, STATE: Amenia, Dutchess County, N.Y.

ALIASES:

CERCLIS ID #: NYD980641559

FISCAL YEAR & QUARTER FOR SCAP:

CONTRACTOR RECOMMENDATION: Listing Site Inspection

EPA RECOMMENDATION: - High priority for further action

PA METHOD SCORE:

WAS SAMPLING CONDUCTED BY CONTRACTOR? Yes groundwater, surface water, sediment, soil

COMMENTS:

There has been a documented presence of solvents in GW, SW, sediment, and soil. One PCB has been found in on-site soils as well as in downstream sediments.

There is a potential for contamination of the groundwater which is used ~~by 6,600~~ people within 3 miles.

There is also a potential for contamination of wetlands and fisheries.

REVIEWER: Gina Ferreira

DATE: Sept. 18, 1992*

REASSESSMENT BY:

RECOMMENDATION:

DATE:

*originally entered 6/87 with no event qualifier

295867