Litton Systems
MD0007152903
1.3
EPA
N/O

Litton Industries

| Sample # | | Description |
|---|---|---|
| 1 | 0-12" | Some blue-green material observed in soil |
| 2. | 0-12" | No discoloration noted |
| 3 | 0-12" | Bluegreen deposits noted |
| 4 | 0-12" | loose type material possible silted |
| 5. | 0-12" | some silt - clayey in lower portion |
| 6 | 0-12" | low area - in drainage - very little rock |
| 7 | 0-12" | shallow gulley or erosion ditch - very little rock - some blue green deposit noted nearby |
| 8 | 0-12" | Very rocky - much discoloration on rocks - blue |
| 9 | 0-12" | rocky - some blue discoloration on rocks |
| 10 | 0-12" | low area - silty - no discoloration noted. |
| 11. | 0-12" | soil in grassy area near drainage - silty - no discolorat |

Well Samples Dale Garner (N end of Mono on west). (S of 2 houses)

Rt 22 Box 1805 Spfd

833-3799

2 Quinn Samples + Airport Salvage from Mono St.

Frank McCrosky

Rt. 6, Box 645, Spfd

833-1512

30289675