45

IOWA DEPARTMENT OF WATER, AIR AND WASTE MANAGEMENT

R.O. 6

WORK REQUEST

ENTERED: 8/13/84 - alice

CPF-00802

REQUEST TO (region or branch): 6	LOCATION OF TASK OR FACILITY	CONTROL NUMBER
REQUESTED BY: BARBARA COOK	EAGLE SIGNAL	WORK APPROVAL: Rod
DATE WORK IS NEEDED: 9/15/84	DAVENPORT	DATE WORK ASSIGNED: 2/16/84
ROUTE RESPONSE THROUGH: Robert Campbell		DATE WORK RETURNED: 9/21/84

RECEIVED AUG 10 1984 IOWA DEPT. OF WATER, AIR AND WASTE MANAGEMENT

DESCRIPTION OF TASK OR REASON FOR REQUEST (attach pertinent documents)

This company has requested to be small quantity generator. Attached is the closure plan prepared by EDER ASSOCIATES. THE PLAN INDICATES THAT ALL CLOSURE ACTIVITIES SHOULD BE COMPLETED. PLEASE INSPECT TO DETERMINE 1) NO REGULATED QUANTITIES OF HW EXIST ON SITE AND 2) ALL SPILLED RESIDUES HAVE BE CLEANED UP.

RECEIVED 84 SEP 21 AM 10 5 DEPARTMENT OF WATER, AIR AND WASTE MANAGEMENT

WORK RESULTS

Include with previous work request of 2/16/84.

#176

R00307826
RCRA RECORDS CENTER

WORK COMPLETED BY	DATE	SUPERVISOR
Steve Hoang Cucker	9/19/84	MVL 9/21/84

WAWM form 54 (Aug 20, 83) (Replaces DEQ form RP-12, which may not be used)

45