Clint

Work Order Tracking

Bulletins (3) Go To Reports Start Center Profile Sign Out Help

BMZAA420SI - Record has been saved.

Find | Select Action

List | Work Order | Plans | Assignments | View | Related Records | Actuals | Safety Plan | Log | Failure Reporting | Specifications | Service Address | Map | Map (Spatial) | Easements | Survey | Asset

Work Order: 21299326 • 12/8 North 5348 drinking fountain stopped up

• Location: 81482 DC0028ZZ-ARIEL RIOS FED BLDG

All Room ID:

1-Person Crew Not Allowed?

Asset:

Asset Tag:

RFID Tag:

Asset Year:

SkySpark EQ ID:

SkySpark EQ Description:

Parent WO:

Classification:

Class Description:

Condition On Arrival:

Above Threshold Cost:

Work Out Of Scope?

• Department / Tenant: 6800 ENVIRONMENTAL PROTECTION AGENCY

Tenant System ID: 5348

Site: 11

Class: WORKORDE

• Work Type: WR

• Work Sub-Type: SERVCALL

• Service Type: OM

Test Type:

Project ID:

GL Account:

• Failure Class: PLUMBING

• Problem Code: WATER FOU

Attachments

Status: WAPPR

Status Date: 12/8/17 9:00 AM

Inherit Status Changes?

Billable to Customer?

Job Details

Job Plan:

PM:

Invoice:

Contract:

Location Details

High Crime?

Hazard?

Seasonal Access?

Priority

Impact Incident?

Asset/Location Priority:

Reported Priority: 3

Work Order Priority: 3

C. PHILLIPS / E. JOHNSON

0700 – 1200 12/14/17

SNAKED OUT DRAIN LINE

SNAKE CABLE IS STUCK

IN DRAIN LINE

C. PHILLIPS 12/14/17

0600 – 0200

REMOVED PIPE AND REMOVED

SNAKE FROM LINE

REMOVED SIGNS

RE-INSTALLED TRAPS, DRAIN CHECKED

FLOW WITH HOT WATER CLEANED UP AREA

COMPLETE

Done + Completed