I.

EPA Region 5 Records Ctr.
356277

Date: 18th March 1987

Time: 8:15 (A.M.) P.M.

Photograph By:

KENNETH PAGE

Location: LPC-1671205030

Sangamon Co.

Springfield / Industrial Chemical

Comments: Photograph taken toward the SE; Drill Rig in background, Ken Bosie + Dale Halford- drillers

location of sample X102

Date: 18th March 1987

Time: 8:40 (A.M.) P.M.

Photograph By:

KENNETH PAGE

Location: LPC-1671205030

Sangamon Co.

Springfield / Industrial Chemical

Comments: Photograph taken toward the S; Bosie and Halford drilling first hole for sample X102

Note: Warning signs are the property of the new tenants in the building (Industrial Chemical), Protection Services Inc.

Date: 18th March 1987

Time: 8:50 (A.M.) P.M.

Photograph By:

KENNETH PAGE

Location: LPC-1671205030

Sangamon Co.

Springfield / Industrial Chemical

Comments: Photograph taken

toward the: Core Sample from

first hole for sample X102

Date: 18th March 1987

Time: 10:05 (A.M.) P.M.

Photograph By:

KENNETH PAGE

Location: LPC-1671205030

Sangamon Co.

Springfield / Industrial Chemical

Comments: Photograph taken

toward the South; Greg Dunn

holding sample X104

Area where paint cans were stored on pallets

Date: 18th March 1987

Time: 10:05 (A.M) P.M.

Photograph By:

KENNETH PAGE

Location: LPC-1671205030

Sangamon Co.

Springfield / Industrial Chemical

Comments: Photograph taken toward the South; Sample location for X104

Date: 18th March 1987

Time: 10:45 (A.M) P.M.

Photograph By:

KENNETH PAGE

Location: LPC-1671205030

Sangamon Co.

Springfield / Industrial Chemical

Comments: Photograph taken toward the: Sample X101, located outside of the east gate on the west side

IV

Date: 18th March 1987

Time: 10:45 (A.M.) P.M.

Photograph By:

KENNETH PAGE

Location: LPC- 1671205030

Sangamon Co.

Springfield / Industrial Chemical

Comments: Photograph taken toward the South; sample X101, outside of EAST GATE

Date: 18th March 1987

Time: 11:00 (A.M.) P.M.

Photograph By:

KENNETH PAGE

Location: LPC- 1671205030

Sangamon Co.

Springfield / Industrial Chemical

Comments: Photograph taken toward the EAST; Sample location for X103, inside tank storage saddles

IL 532-0603
L/NPC 24 6/78

V.

Date: 18th March 1987

Time: 11:30 (A.M.) P.M.

Photograph By:

KENNETH PAGE

Location: LPC- 1671205030

Sangamon Co.

Springfield / Industrial Chemical

Comments: Photograph taken toward the South; Drill Rig drilling second bore hole

Date: 18th March 1987

Time: 11:40 (A.M.) P.M.

Photograph By:

KENNETH PAGE

Location: LPC- 1671205030

Sangamon Co.

Springfield / Industrial Chemical

Comments: Photograph taken toward the: Second bore hole Core sample

IL 532-0603
L/NPC 24 6/78

VI.

Date: 18th March 1987

Time: 12:30 A.M. P.M.

Photograph By:

KENNETH PAGE

Location: LPC- 167120 5030

Sangamon Co.

Springfield / Industrial Chemical

Comments: Photograph taken

toward the South

Note: Two piles of soil are location for the first and second bore holes for sample X102. Auger is still in the third bore hole location

Date:

Time: A.M. P.M.

Photograph By:

Location: LPC-

Co.

/

Comments: Photograph taken

toward the

IL 532-0603
L/NPC 24 6/78