PIC NO. 91706
FRAME NO. 5
UNDERGROUND PIPELINE SCAR
U.S. ROUTE 40
STANDING LIQUID
Silver Creek
UNION PACIFIC RAILROAD
STAIN
TAILINGS (COVERED)
TAILINGS (NOT COVERED)
PIT
PITS
LANDFILL
PIPELINE
COVER MATERIAL
SL
DIVERSION DITCH
FILL (COVERED)
TAILINGS (COVERED)
OLD ROAD BED
HIGHWAY CONSTRUCTION
LEGEND
FLOW
DRAINAGE
RAILWAY
EXCAVATION/PIT
MOUNDED MATERIAL
FENCED SITE BOUNDARY
FENCE
BERM, DIKE
EPA Environmental Monitoring Systems Laboratory-Las Vegas
7116 - R8 SDMS
RICHARDSON FLAT TAILINGS
PARK CITY, UTAH
PIC 91706
DATE FLOWN: JUNE 3, 1988
SOURCE: EMSL-LV FRAME NO. 5
APPROX. SCALE 1 inch = 250 feet
-N-