IL-132-07

Illinois Environmental Protection Agency
Richard H. Briceland, Director
2200 Churchill Road, Springfield, Illinois 62706

EPA Region 5 Records Ctr.
321828

Telephone: 312/345-9760
Address Reply To:
Suite 1205
1701 First Avenue
Maywood, Illinois 60153

August 4, 1977

COMMONWEALTH EDISON - PCB Sampling
Technical Center - Maywood

Mr. John H. Hughes, Director
Water Quality
Commonwealth Edison Company
Post Office Box 767
Chicago, Illinois 60690

Dear Sir:

Enclosed please find the Inspection Report indicating Agency results of PCB analyses performed on samples obtained during our joint sampling survey conducted on April 18, 1977 at your Maywood Technical Center.

We would appreciate receipt of your PCB analyses performed on duplicate samples obtained during the survey.

Upon our receipt and review of your analyses, we will contact you regarding the significance of the levels obtained and subsequent Agency actions.

Very truly yours,
DIVISION OF WATER POLLUTION CONTROL

Edward L. Marek

Edward L. Marek, Manager, Region II
Field Operations Section, DWPC

ELM:LEZ:jj
cc Records Unit, FOS/DWPC

cc -Records Unit, FOS/DWPC
-PCB General File

MJS
~~CLH~~
RAS

INSPECTION NOTES

COMMONWEALTH EDISON
Technical Center - Maywood

PCB Sampling

DATE: April 18, 1977

ACCOMPANIED BY: R.A. Schacht, IEPA
R. Cascarano, Com. Ed.
P. Noska, Com. Ed.
R. Phelan, Com. Ed.

WEATHER: Sunny, Temperature about 80°F.

On the above date a sampling inspection was conducted at the Commonwealth Edison Tech Center site in order to evaluate levels of PCB's (polychlorinated biphenyls) in both soils on the plant site and sediments in the Des Plaines River. Askarel filled transformers are stored on the plant site and previous inspections had determined that detectable levels of PCB's were present in storm water discharges and in one soil sample obtained from the facility site.

The soil samples were obtained from the specified areas from within 3 inches of the soil surface and transferred to the sample bottles with use of a hand garden tool. Two replicate samples, from each area, were provided for Commonwealth Edison. Their Technical Center had recently acquired gas chromatographic analytical equipment and they also intended to send one of the samples for private laboratory analysis.

The river sediment samples were obtained by R. Schacht, by use of a standard sieve.

The nine samples were iced after collection and transported, by the writter, the next day to our Springfield laboratories for analysis.

The following samples were obtained:

NO.1: obtained from the soil immediately northeast of a storm drain which receives runoff from the storage yards. See the attached drawing for location of the soil samples. This area is located west of transformer storage areas. Lab result=43.1ppm.

NO.2: obtained from the soil at the south end of the facility from within a row of stored transformers. This row presently stores all the askarel filled transformers at the facility site. The sample location was about 75 feet north of the south boundary fence. Lab result=14.3ppm.

NO.3: obtained from the soil at the east end of the facility from within a row of stored, oil filled (non-askarel), transformers. The sample location was about 15 feet north of a boundary fence. Lab result=86.4ppm.

NO.4: obtained from the soil at the northeast end of the facility where previously dumpsters, which received damaged capacitors (askarel filled), were stored. Lab result=210.0ppm.

NO.5: Des Plaines River sediment just downstream of the storm sewer located south of the Chicago Great Western Railroad. This storm sewer discharges, in addition to storm water from the north end of the Tech Center, storm water from local drainage and combined sewer overflows from the Maywood sewer system. Lab result=6.0ppm.

NO.6: Des Plaines River sediment, along the west bank, about 40 feet upstream of the Chicago Great Western Railroad. Lab result=1.65ppm.

NO.7: Des Plaines River sediment just downstream of IDOT pumping station located immediately south of I-90. This pumping station discharges, in addition to storm water from the south end of the Tech Center, storm water from the I-90 expressway system. Lab result=4.08ppm.

NO.8: Des Plaines River sediment about 25 feet upstream of Roosevelt Road. The sample was obtained from along the west bank. Lab result=2.5ppm.

NO.9: a soil sample obtained from the Cook County Forest Preserve (Miller Meadows) about 30 feet south of Roosevelt Road and 150 feet west of the Des Plaines River. Lab result=0.23ppm.

L.E. Ziemba, Environmental
Protection Engineer, Maywood

LEZ:jj
7/28/77


SAMPLE NO. 4
SAMPLE NO. 3
SAMPLE NO. 1
SAMPLE NO. 2
N
18000 GALS
20000 GALS
15000 GALS
28649 GALS
16804 GALS
17899 GALS
14944 GALS
9484 GALS
27239 GALS
31553 GALS
1310 GALS
2293 GALS
6195 GALS
16600 GALS
9016 GALS
8411 GALS
10052 GALS
4975 GALS
8000 GALS
17553 GALS
14194 GALS
STORAGE AREA #1
STORAGE AREA #2
STORAGE AREA #3

#1-LEZ

D007636

SPECIAL ANALYSIS FORM

ime Collected 8:30 AM

Sub-Basin MAYWOOD FOS

ate Collected 4/18/77

Collector L. E. ZIEMBA/SCHACHT

acility Name: COMM ED.

Facility Number: TECH CENTER

File Town MAYWOOD

ream Name(s)

Stream Code:

ource of Sample: (Exact Location)

SOIL SAMPLE. SW AREA OF PLANT

RECEIVED
ILL. ENVIRONMENTAL PROTECTION AGENCY

hysical Observations, Remarks:

JUN 1977

DIV. WATER POLLUTION CONTROL
FIELD OPERATIONS SECTION - REG. 2C

ow	Field Dissolved Oxygen	Field pH	Field Temp.

Arsenic	Coliform/100ml	BOD
Barium	Fecal Coliform 100 ml	COD
Boron	Fecal Strep 100 ml	TS/EC
Cadmium	Algae (Total) /ml	Susp.Solids
Copper	Ammonia (N)	Vol.Susp.Solids
Chromium (tri)	Organic Nitrogen (N)	pH (units)
Chromium (hex)	Nitrate + Nitrite(N)	Turbidity (JTU)
Iron (Total)	Phosphorus (P)	Hardness
Iron (Dissolved)	Chloride	Alkalinity
Lead	Fluoride	Total Acidity
Manganese	Sulfate	Free Acidity
Mercury (ppb)	Cyanide	Oil
Nickel	MBAS	43,100 ug/kg PPB TOTAL PCB'S Other (Specify)
Selenium	Phenol (ppb)	43.1 ug/g PPM
Silver		
Zinc		

esults in mg/l unless
therwise noted.

100% Recycled Paper

Transported by: L. E. Ziemba

Received by:

Transported by:

Received by:

FOR LAB USE ONLY

D007636

Lab Number: Rec'd by: DRH

Date sample rec'd: APR 19 1977 Time: 1:30 pm

Date analysis completed: 6/6/77

Date results forwarded: 6/6/77

Total Tests requested: Tests run: 7

Lab Section: Springfield Supervisor: J. Hurley

73

#7-LLL

SPECIAL ANALYSIS FORM

D007637

Time Collected 8:45 A.M.

Sub-Basin MAYWOOD - FOS

Date Collected 4/18/77

Collector L. E. ZIEMBA / SCHACHT

Facility Name: COMM. ED. TECH CENTER

Facility Number:

File Town MAYWOOD

Stream Name(s)

Stream Code:

Source of Sample: (Exact Location)

SOIL SAMPLE, SOUTH END OF PROPERTY

RECEIVED
ILL. ENVIRONMENTAL PROTECTION AGENCY
JUN 09 1977
DIV. WATER POLLUTION CONTROL
FIELD OPERATIONS SECTION FOR 2C

Physical Observations, Remarks:

Flow	Field Dissolved Oxygen	Field pH	Field Temp.

Arsenic	Coliform/100ml	BOD
Barium	Fecal Coliform 100 ml	COD
Boron	Fecal Strep 100 ml	TS/EC
Cadmium	Algae (Total) /ml	Susp.Solids
Copper	Ammonia (N)	Vol.Susp.Solids
Chromium (tri)	Organic Nitrogen (N)	pH (units)
Chromium (hex)	Nitrate + Nitrite(N)	Turbidity (JTU)
Iron (Total)	Phosphorus (P)	Hardness
Iron (Dissolved)	Chloride	Alkalinity
Lead	Fluoride	Total Acidity
Manganese	Sulfate	Free Acidity
Mercury (ppb)	Cyanide	Oil
Nickel	MBAS	14.3 ug/g PPM TOTAL PCB'S Other (Specify)
Selenium	Phenol (ppb)	
Silver		
Zinc		

Results in mg/l unless otherwise noted.

100% Recycled Paper

Transported by: L. E. Ziemba

Received by:

Transported by:

Received by:

FOR LAB USE ONLY

D007637

Lab Number: Rec'd by: DRH

Date sample rec'd: APR 19 1977 Time: 1:30 pm

Date analysis completed: 6/6/77

Date results forwarded: 6/6/77

Total Tests requested: Tests run: 7

Lab Section: Springfield Supervisor: J. Hurley

73

#2-LEZ

SPECIAL ANALYSIS FORM

D007638

ime Collected 9:00 A.M.

Sub-Basin MAYWOOD - FOS

ite Collected 4/18/77

Collector L.E. ZIEMBA/SCHACAT

acility Name: COMM. ED. TECH CENTER

Facility Number:

File Town MAYWOOD

tream Name(s)

Stream Code:

urce of Sample: (Exact Location)

SOIL SAMPLE - EAST END OF PROPERTY

RECEIVED
ILL. ENVIRONMENTAL PROTECTION AGENCY
JUN 0 [illegible]
DIV. WATER POLLUTION CONTROL

ysical Observations, Remarks:

ow	Field Dissolved Oxygen	Field pH	Field Temp.

Arsenic	Coliform/100ml	BOD
Barium	Fecal Coliform 100 ml	COD
Boron	Fecal Strep 100 ml	TS/EC
Cadmium	Algae (Total) /ml	Susp.Solids
Copper	Ammonia (N)	Vol.Susp.Solids
Chromium (tri)	Organic Nitrogen (N)	pH (units)
Chromium (hex)	Nitrate + Nitrite(N)	Turbidity (JTU)
Iron (Total)	Phosphorus (P)	Hardness
Iron (Dissolved)	Chloride	Alkalinity
Lead	Fluoride	Total Acidity
Manganese	Sulfate	Free Acidity
Mercury (ppb)	Cyanide	Oil
Nickel	MBAS	86.4 ug/g PPM TOTAL PCB'S Other (Specify)
Selenium	Phenol (ppb)	
Silver		
Zinc		

esults in mg/l unless otherwise noted.

100% Recycled Paper

Transported by: L.E. Ziemba

Received by:

Transported by:

Received by:

FOR LAB USE ONLY

D007638

Lab Number: Rec'd by: DRH

Date sample rec'd: APR 19 1977 Time: 1:30pm

Date analysis completed: 6/6/77

Date results forwarded: 6/6/77

Total Tests requested: Tests run: 7

Lab Section: Springfield J. Hurley Supervisor:

/73

#7-LEZ

SPECIAL ANALYSIS FORM

D007639

ime Collected 9 05 A.M

Sub-Basin MAYWOOD FOS

ate Collected 4/18/77

Collector L.E. ZIEMBA/SCHACHT

acility Name: COMM. ED. TECH CENTER

Facility Number:

File Town MAYWOOD

tream Name(s)

Stream Code:

ource of Sample: (Exact Location)

SOIL SAMPLE - NORTHEAST AREA OF SITE

RECEIVED
ILL. ENVIRONMENTAL PROTECTION AGENCY
JUN 09 1977
DIV. WATER POLLUTION CONTROL
FIELD SPEC. ... REG. 2C

ysical Observations, Remarks:

low	Field Dissolved Oxygen	Field pH	Field Temp.

Arsenic	Coliform/100ml	BOD
Barium	Fecal Coliform 100 ml	COD
Boron	Fecal Strep 100 ml	TS/EC
Cadmium	Algae (Total) /ml	Susp.Solids
Copper	Ammonia (N)	Vol.Susp.Solids
Chromium (tri)	Organic Nitrogen (N)	pH (units)
Chromium (hex)	Nitrate + Nitrite(N)	Turbidity (JTU)
Iron (Total)	Phosphorus (P)	Hardness
Iron (Dissolved)	Chloride	Alkalinity
Lead	Fluoride	Total Acidity
Manganese	Sulfate	Free Acidity
Mercury (ppb)	Cyanide	Oil
Nickel	MBAS	210. ug/g PPM TOTAL PCB'S Other (Specify)
Selenium	Phenol (ppb)	
Silver		
Zinc		

esults in mg/l unless
therwise noted.

100% Recycled Paper

Transported by: J.E. Zieb

Received by:

Transported by:

Received by:

FOR LAB USE ONLY

D007639

Lab Number: Rec'd by: DRH

Date sample rec'd: APR 19 1977 Time: 1:30pm

Date analysis completed: 6/6/77

Date results forwarded: 6/6/77

Total Tests requested: Tests run: 7

Lab Section: Springfield J. Hurley Supervisor:

73

5-62

D007640

SPECIAL ANALYSIS FORM

Time Collected 9 30 AM.

Sub-Basin MAYWOOD - FCS

Date Collected 4/18/77

Collector L. E. ZIEMSA / R. SCHACHT

Facility Name: COMM ED. TECH CENTER

Facility Number:

File Town MAYWOOD

Stream Name(s) DES PLAINES R

Stream Code:

Source of Sample: (Exact Location)

RIVER SEDIMENT @ OUTFALL (WEST BANK) OUTSIDE SPILLWAY JUST DOWNSTREAM OF R.R. TRESSEL

Physical Observations, Remarks: BLACK, SLUDGE LIKE DEPOSITS

RECEIVED
U.S. ENVIRONMENTAL PROTECTION AGENCY
JUN 06 1977
WATER POLLUTION CONTROL
FIELDS SECTION - REG. 20

Flow	Field Dissolved Oxygen	Field pH	

Arsenic	Coliform/100ml	BOD
Barium	Fecal Coliform 100 ml	COD
Boron	Fecal Strep 100 ml	TS/EC
Cadmium	Algae (Total) /ml	Susp.Solids
Copper	Ammonia (N)	Vol.Susp.Solids
Chromium (tri)	Organic Nitrogen (N)	pH (units)
Chromium (hex)	Nitrate + Nitrite(N)	Turbidity (JTU)
Iron (Total)	Phosphorus (P)	Hardness
Iron (Dissolved)	Chloride	Alkalinity
Lead	Fluoride	Total Acidity
Manganese	Sulfate	Free Acidity
Mercury (ppb)	Cyanide	Oil
Nickel	MBAS	6000 ug/kg (ppb) 6.0 ug/g PPM TOTAL PCB'S Other (Specify)
Selenium	Phenol (ppb)	
Silver		
Zinc		

Results in mg/l unless otherwise noted.

100% Recycled Paper

Transported by: J. E. Ziemsa

Received by:

Transported by:

Received by:

FOR LAB USE ONLY

Lab Number: D007640 Rec'd by: DRH

Date sample rec'd: MAR 19 1977 Time: 1:30pm

Date analysis completed: 6/6/77

Date results forwarded: 6/6/77

Total Tests requested: Tests run: 1

Lab Section: Springfield Supervisor: J. Hurley

73

#6-LEE

D007641

SPECIAL ANALYSIS FORM

ime Collected 9 45 AM

Sub-Basin MAYWOOD FOS

ate Collected 4/18/77

Collector ZIEMBA / SCHACHT

acility Name: COMM ED TECH CENTER

Facility Number:

File Town MAYWOOD

tream Name(s) DES PLAINES R.

Stream Code:

ource of Sample: (Exact Location)

RIVER SEDIMENT, ALONG WEST BANK, ≈ 40' UPSTREAM OF R.R. TRESSEL

RECEIVED
ILL. ENVIRONMENTAL PROTECTION AGENCY
JUN 09 1977
DIV. WATER POLLUTION CONTROL
FIELD OPERATIONS SECTION - REG. 2C

ysical Observations, Remarks: BLACK, SLUDGE LIKE DEPOSITS

ow	Field Dissolved Oxygen	Field pH	Field Temp.

Arsenic	Coliform/100ml	BOD
Barium	Fecal Coliform 100 ml	COD
Boron	Fecal Strep 100 ml	TS/EC
Cadmium	Algae (Total) /ml	Susp.Solids
Copper	Ammonia (N)	Vol.Susp.Solids
Chromium (tri)	Organic Nitrogen (N)	pH (units)
Chromium (hex)	Nitrate + Nitrite(N)	Turbidity (JTU)
Iron (Total)	Phosphorus (P)	Hardness
Iron (Dissolved)	Chloride	Alkalinity
Lead	Fluoride	Total Acidity
Manganese	Sulfate	Free Acidity
Mercury (ppb)	Cyanide	Oil
Nickel	MBAS	Other (Specify)
Selenium	Phenol (ppb)	
Silver		
Zinc		

1650 ug/kg (ppb) TOTAL PCB'S
1.65 ug/g PPM

esults in mg/l unless
therwise noted.

100% Recycled Paper

Transported by: J. P. Zwick
Received by:
Transported by:
Received by:

FOR LAB USE ONLY

D007641

Lab Number: Rec'd by: DRH
Date sample rec'd: APR 19 1977 Time: 1:30 pm
Date analysis completed: 6/6/77
Date results forwarded: 6/6/77
Total Tests requested: Tests run: 7
Lab Section: Springfield Supervisor: J. Hurley

'73

#1-LEZ

SPECIAL ANALYSIS FORM

D007642

ime Collected 10 20 A.M

Sub-Basin MAYWOOD - FOS

ate Collected 4/18/77

Collector ZIEMBA / SCHACHT

acility Name: Comm. ED TECH CENTER

Facility Number:

File Town MAYWOOD

tream Name(s) DES PLAINES R.

Stream Code:

ource of Sample: (Exact Location)

RIVER SEDIMENT @ DOWNSTREAM EDGE OF IDOT PUMPING STATION OUTFALL (≈ 70' DOWNSTREAM OF I-90).

ysical Observations, Remarks: BLACK SLUDGE-LIKE DEPOSITS

RECEIVED
ILL. ENVIRONMENTAL PROTECTION AGENCY
JUN 09 1977
DIV. WATER POLLUTION

ow	Field Dissolved Oxygen	Field pH	Field Temp.

Arsenic	Coliform/100ml	BOD
Barium	Fecal Coliform 100 ml	COD
Boron	Fecal Strep 100 ml	TS/EC
Cadmium	Algae (Total) /ml	Susp.Solids
Copper	Ammonia (N)	Vol.Susp.Solids
Chromium (tri)	Organic Nitrogen (N)	pH (units)
Chromium (hex)	Nitrate + Nitrite(N)	Turbidity (JTU)
Iron (Total)	Phosphorus (P)	Hardness
Iron (Dissolved)	Chloride	Alkalinity
Lead	Fluoride	Total Acidity
Manganese	Sulfate	Free Acidity
Mercury (ppb)	Cyanide	Oil
Nickel	MBAS	Other (Specify)
Selenium	Phenol (ppb)	
Silver		
Zinc		

4080 ug/kg PPB
4.08 ug/g PPM
TOTAL PCB'S

esults in mg/l unless otherwise noted.

100% Recycled Paper

Transported by: J. E. Zimbo

Received by:

Transported by:

Received by:

FOR LAB USE ONLY

D007642

Lab Number: Rec'd by: DRH

Date sample rec'd: APR 19 1977 Time: 1:30pm

Date analysis completed: 6/6/77

Date results forwarded: 6/6/77

Total Tests requested: Tests run: 7

Lab Section: Springfield J. Hurley Supervisor:

'73

#3 LCZ

SPECIAL ANALYSIS FORM

D007643

ime Collected 10 40 A.M.

Sub-Basin MAYWOOD-FOS

ate Collected 4/18/77

Collector ZIEMBA / SCHACHT

acility Name: COMM. ED TECH CENTER

Facility Number:

File Town MAYWOOD

tream Name(s)

Stream Code:

ource of Sample: (Exact Location)

RIVER SEDIMENT, ALONG WEST BANK, ≈ 25' UPSTREAM OF ROOSEVELT RD; TWO OUTFALLS, NOT DISCHARGING, @ LOCATION

hysical Observations, Remarks: BLACK, SLUDGE-LIKE DEPOSITS

RECEIVED
ILL. ENVIRONMENTAL PROTECTION AGENCY
JUN 0 1977
DIV. WATER POLLUTION CONTROL
FIELD OPERATIONS SECTION

ow	Field Dissolved Oxygen	Field pH	Field Temp.

Arsenic	Coliform/100ml	BOD
Barium	Fecal Coliform 100 ml	COD
Boron	Fecal Strep 100 ml	TS/EC
Cadmium	Algae (Total) /ml	Susp.Solids
Copper	Ammonia (N)	Vol.Susp.Solids
Chromium (tri)	Organic Nitrogen (N)	pH (units)
Chromium (hex)	Nitrate + Nitrite(N)	Turbidity (JTU)
Iron (Total)	Phosphorus (P)	Hardness
Iron (Dissolved)	Chloride	Alkalinity
Lead	Fluoride	Total Acidity
Manganese	Sulfate	Free Acidity
Mercury (ppb)	Cyanide	Oil
Nickel	MBAS	Other (Specify)
Selenium	Phenol (ppb)	
Silver		
Zinc		

2530 ug/kg ppb TOTAL PCB'S
2.5 ug/g PPM

esults in mg/l unless otherwise noted.

100% Recycled Paper

Transported by: J. E. Ziemba

Received by:

Transported by:

Received by:

FOR LAB USE ONLY

D007643

Lab Number: Rec'd by: DRH

Date sample rec'd: APR 19 1977 Time: 1:30 pm

Date analysis completed: 6/6/77

Date results forwarded: 6/6/77

Total Tests requested: Tests run: 7

Lab Section: Springfield J. Hurley Supervisor:

/73

#7-CEZ

D007644

SPECIAL ANALYSIS FORM

ime Collected 10 45 A.M.

Sub-Basin MAYWOOD - FOS

ate Collected 4/18/77

Collector ZIEMBA / SCHMEDT

acility Name: COMM. ED TECH CENTER

Facility Number:

File Town MAYWOOD

tream Name(s)

Stream Code:

ource of Sample: (Exact Location)

SURFACE SOIL (MILLER MEADOWS FOREST PRESERVE) ≈ 30' SOUTH OF ROOSEVELT ROAD + 150' WEST OF DESPLAINES R

hysical Observations, Remarks: HUMUS LIKE SOIL

RECEIVED

ow	Field Dissolved Oxygen	Field pH	Field Temp

Arsenic	Coliform/100ml	BOD
Barium	Fecal Coliform 100 ml	COD
Boron	Fecal Strep 100 ml	TS/EC
Cadmium	Algae (Total) /ml	Susp.Solids
Copper	Ammonia (N)	Vol.Susp.Solids
Chromium (tri)	Organic Nitrogen (N)	pH (units)
Chromium (hex)	Nitrate + Nitrite(N)	Turbidity (JTU)
Iron (Total)	Phosphorus (P)	Hardness
Iron (Dissolved)	Chloride	Alkalinity
Lead	Fluoride	Total Acidity
Manganese	Sulfate	Free Acidity
Mercury (ppb)	Cyanide	Oil
Nickel	MBAS	Other (Specify) TOTAL PCB'S 23.3 ug/kg PPB 0.23 ug/g PPM 0.23 mg/g
Selenium	Phenol (ppb)	
Silver		
Zinc		

esults in mg/l unless otherwise noted.

100% Recycled Paper

Transported by: J. E. Ziemba

Received by:

Transported by:

Received by:

FOR LAB USE ONLY

D007644

Lab Number: Rec'd by: DRH

Date sample rec'd: APR 19 1977 Time: 1:30pm

Date analysis completed: 6/6/77

Date results forwarded: 6/6/77

Total Tests requested: Tests run: 7

Lab Section: Springfield J. Hurley Supervisor:

'73



COMMONWEALTH EDISON CO.
TECHNICAL CENTER &
DES PLAINES VALLEY AREA HEADQUARTERS
1319-1505 SO. FIRST AVE.
MAYWOOD, ILL.
A. GIEDRAMS
Rec'd from DISK SUSTICH
PCO ON 9/13/77
ADAMS ST.
STA #2A
DOWNSTREAM SANITARY
PARKING LOT
STA #1B
STORM
27" MAYWOOD STORM
D.V.A. HQ.
GARAGE
TECHNICAL CENTER BUILDING
12" SAN.
STA #1A
UPSTREAM SANITARY
MATERIAL STORAGE AREA
TRANSFORMER OIL
TRANSFORMER STORAGE
18" STORM
15" STORM
STA #2B
STORM
INTERCONTINENTAL BUILDING
PARKING LOT
EISENHOWER
EXPRESSWAY
EXPY. STORM SEWER FROM MANNHEIM RD.
EXPY. STORM FROM CENTRAL
D.O.T. PUMP STATION #4
NOT TO
MSD INTERCEPTING DES PLAINES
DES PLAINES RIVER
CONGRESS ST.
HARRISON ST.