7530-00-222-0078
FEDERAL SUPPLY SERVICE

Memoranda

Chempro - Pier 91

Martha Rosenberg

FOIA EXEMPT

WA 2917
7/15/86
1f
↓
49

Chempro
Pier 91
7/15/86

Picture log:





photo 4.

near office building

Oil/water separator

pictures 5 & 6

black grill + hoses



Photo 7



- Receiving Station for waste oil looking North.

Photo 9 & 8 Valve System
oil water seperator



adjoins water system
underground.

photo looking
South

Photo 10 - Operations Office
lab sink, emergency
warning signs,
Centrifuge.



Tanks
photo 11 + 12
(106, 108, 100, 112)

Tank 106 Sludge from other tanks.

Tank 12 + 13

94, 96, ~~=~~98



Photo 14



Photo is North



Isolation tank
Haz. waste tank

photo 16



Not used

↑

photo No.

photo 17

Sludge tank



looking south

photo 18
Tanks 115, 116, 117



haz. waste tanks.

↑ south view

photo 19



photo.

photo 20 & 21

Pipe alley

↑ South



photo 22

Overview of tanks



photo east.

photo 23

Close up of haz. waste tank. Rust spots

Role 2

photos 1-~~3~~4

2 of sludge barrel

sludge seperator

near tank 112

Note: Role 1

Overexposed pictures

22, 23, 24 when

trying to remove

film.

photo 5

Process drums



"Very sloppy material"

photo 6 + 7
signage + fencing

photo 8 –

Empty containers –
blue color
in small shack

photo 9

black drums for

sludge - empties -

piled near fence.

photo 10

Old recycling tanks — from top.

photo 11

Old recycling tanks from side view

photo 12 & 13

Rec Tank.



photo 14 + 15

Inside - chemical tanks are stored

photo 16

Old boiler chemical drums, caustic

Dark will probably not come out.

photo 17

Foam system for
fire, ~~#~~ one each tank

PHOTO 18 — END

FRONT OF OFFICE BUILDING — ~~to~~ unloading, signage, truck, workers', etc.