

Source:
Base map taken from "Figure 2 - Site and Sample Location Map" in June 1999
Hercules Marine Service Site Characterization Report prepared by LT Environmental, Inc.

GULFCO MARINE MAINTENANCE
FREEPORT, BRAZORIA COUNTY, TEXAS

Figure 2

PROPOSED SHALLOW SOIL BORINGS

PROJECT: 1259	BY: ZGK	REVISIONS
DATE: APRIL, 2005	CHECKED: EFP	

PASTOR, BEHLING & WHEELER, LLC
CONSULTING ENGINEERS AND SCIENTISTS

887329