Photographer / Witness PHOTO #1

G. Duncan / D. Vaughn

Date / Time / Direction

3-11-81 / 11:00 / SE

Comments: surface impoundment in foreground; upperleft background shows seperator tank and overflow trough

Photographer / Witness PHOTO #2

G. Duncan / D. Vaughn

Date / Time / Direction

3-11-81 / 11:05 / NW

Comments: suction line from waste water impoundments to boilers.

Photographer / Witness PHOTO #3

G. Duncan / D. Vaughn

Date / Time / Direction

3-11-81 / 11:07 / ~~SW~~ East

Comments: looking towards steam cleaning boilers and Northern part of waste impoundments.

9418112

Photographer / Witness PHOTO #4

G. Duncan / D. Vaughn

Date / Time / Direction

3-11-81 / 11:10 / W

Comments: View of both pits and levee

Photographer / Witness PHOTO #5

G. Duncan / D. Vaughn

Date / Time / Direction

3-11-81 / 11:17 / SE to S

Comments: panarama of pits, including separator, boiler at extreme left, and storage tanks at right.

Photographer / Witness

Date / Time / Direction

Comments: