ADEQ
Hazardous Waste Division
Technical Branch
Trip Report

Project	Former Cedar Chemical Facility
Location	West Helena, AR
Date	03/01/2012
Time	day trip
Reason	Observe site activities
ADEQ personnel	Clay McDaniel, Jim Rigg, Jeremiah Jackson
Facility personnel	Gary Hill
Activity Summary	We walked around the facility with Gary Hill as he updated us with site activities and planned future activities.
Action Items Summary	• Unit 1 is in operation by *EnviroTech Industries*. They produce peroxyacetic acid (PAA) to be used in chicken cleaning. The attached pictures document the operations. • A soil pile was placed on the concrete foundation where Unit 4 used to be. It had a distinct odor (see photo # 8). Gary said this soil was excavated from the Unit 1 area. Jim recommended that it should be sampled and disposed accordingly.
Anticipated follow-up	.
Other	

Route to:

ADEQ personnel review	**date**
Annette Cusher	3/7/11
Tammie Hynum	

9459523

Arkansas Department of Environmental Quality
Official Photograph Log

Worker Grinding Sheet Metal Near Unit 1	
Photo # 1	**Photographer**: Clay McDaniel, ADEQ
Date: Thursday, March 1, 2012	**Witness**: Jeremiah Jackson, ADEQ

Acetic Acid Storage Tank	
Photo # 2	**Photographer**: Clay McDaniel, ADEQ
Date: Thursday, March 1, 2012	**Witness**: Jeremiah Jackson, ADEQ

Arkansas Department of Environmental Quality
Official Photograph Log

Hydrogen Peroxide Storage Tank	
Photo # 3	**Photographer**: Clay McDaniel, ADEQ
Date: Thursday, March 1, 2012	**Witness**: Jeremiah Jackson, ADEQ

Empty Poly Totes to be Used in Transporting Product	
Photo # 4	**Photographer**: Clay McDaniel, ADEQ
Date: Thursday, March 1, 2012	**Witness**: Jeremiah Jackson, ADEQ

Arkansas Department of Environmental Quality
Official Photograph Log

Corrosive Label on Poly Tote (filled ½ way with 20% nitric acid)	
Photo # 5	**Photographer**: Clay McDaniel, ADEQ
Date: Thursday, March 1, 2012	**Witness**: Jeremiah Jackson, ADEQ

Empty Poly Totes to be Used in Transporting Product	
Photo # 6	**Photographer**: Clay McDaniel, ADEQ
Date: Thursday, March 1, 2012	**Witness**: Jeremiah Jackson, ADEQ

Arkansas Department of Environmental Quality
Official Photograph Log

Empty Poly Tank with Labeling	
Photo # 7	**Photographer**: Clay McDaniel, ADEQ
Date: Thursday, March 1, 2012	**Witness**: Jeremiah Jackson, ADEQ

Soil Pile Originating from Unit 1 Excavation	
Photo # 8	**Photographer**: Clay McDaniel, ADEQ
Date: Thursday, March 1, 2012	**Witness**: Jeremiah Jackson, ADEQ