ADEQ
Hazardous Waste Division
Technical Branch
Trip Report

Project	Former Cedar Chemical Facility
Location	West Helena, AR
Date	06/27/2012
Time	day trip
Reason	Observe Site Conditions
ADEQ personnel	Clay McDaniel, Jim Rigg, Mark Lawler
Facility personnel	Gary Hill – Harcross employee Stanley Herrington – Harcross Site Manager
Activity Summary	Took tour of the facility to observe compliance
Action Items Summary	• We toured the admin building to observe the status of the documents. There are estimated to be 680 boxes of documents and they are in good condition. Sagging ceiling tiles were observed (see photo #1) but the apparent leak has not yet impacted the documents. • An unidentified monitoring well did not have a lock on it (see photo #2). • The soil pile from excavation of the sump is still located on the former Unit 4 foundation (see photo #3). It has been 119 days between when it was 1st discovered and this site visit. Stan said a sample from the soil pile was taken for analysis to ETC in Memphis. It was then supposed to be taken to clean harbors, but is still in negotiation between clean harbors and John Peiserich. • There are around 18 buckets of IDW purge water from July 2010 sampling event. Each bucket was labeled to identify the monitoring well it came from • Harcross has fixed cracked asphalt that was requested in ADEQ letter dated May 31, 2012 (see photo #4).
Anticipated follow-up	Harcross has not provided ADEQ with bi-weekly updates on the status of the soil pile or met the 45 day deadline to respond to remove the IDW (expired on 05/18/12). A letter should be sent to Harcross to site them of their failure to follow up ADEQ's request.
Other	

Route to:

ADEQ personnel review	date

9459940

Annette Cusher	7/6/2012
Tammie Hynum	

Arkansas Department of Environmental Quality
Official Photograph Log

Ceiling In Admin Building	
Photo # 1	**Photographer**: Clay McDaniel, ADEQ
Date: Wednesday, June 27, 2012	**Witness**: Mark Lawler, ADEQ

Monitoring Well With No Lock (located in the boneyard area)	
Photo # 2	**Photographer**: Clay McDaniel, ADEQ
Date: Wednesday, June 27, 2012	**Witness**: Mark Lawler, ADEQ

Soil Pile from Sump Excavation (located on the former Unit 4 footprint)	
Photo # 3	**Photographer**: Clay McDaniel, ADEQ
Date: Wednesday, June 27, 2012	**Witness**: Mark Lawler, ADEQ

Arkansas Department of Environmental Quality

Official Photograph Log

Newly Paved Area to Replace Cracked Asphalt	
Photo # 4	**Photographer**: Clay McDaniel, ADEQ
Date: Wednesday, June 27, 2012	**Witness**: Mark Lawler, ADEQ