REVIEW

Potential Hazardous Waste Site - Site Inspection Report

Site Name TOTAL PETROLEUM COMP

Site Location ARDMORE, OK. CARTER, COUNTY

Site Number OK 1589 Date of Survey 4/10/84

REPORT 9/10/84

Inspected by ____ State ____ FIT ____ TAT ____

Other (specify) ____

Date rec'd by Water Supply Branch 3/12/85

Type samples: RESULTS 7/5/84

✓ SOIL ✓ on-site ____ off-site

___ SURFACE WATER ____ on-site ____ off-site

___ GROUND WATER ____ on-site ____ off-site

___ DRINKING WATER ____ on-site ____ off-site

Type contaminant(s):

✓ ORGANICS ✓ INORGANICS ___ RADIONUCLIDES ___ MICROBIOLOGICAL

Summary:

1. ALL INORGANICS W/I AMBIENT BACKGROUND LEVELS
2. COULD NOT LOCATE RESIDENTIAL WELLS ON THE MAP
3. IF WELLS ARE LOCATED IN DIRECTION OF GROUND WATER FLOW, ONE SHOULD BE INCLUDED AS PROPOSED SAMPLE LOCATION.

O. [illegible] 3/15/85

Edgar A. Jeffery 2/13/85

Signature and Date

6W-SP

9532451