LyondellBasell Fire

Photo Log

Description: 536 Crude Processing Unit stormwater grate located near the northeast corner.

Category: Site Photo

Latitude:

Date Taken: 5/18/2010

Longitude:

Tags:

Description: 536 Crude Processing Unit stormwater grate located at the northwest corner.

Category: Site Photo

Latitude:

Date Taken: 5/18/2010

Longitude:

Tags:

Description: 536 Crude Processing Unit; northwest corner.

Category: Site Photo

Latitude:

Date Taken: 5/18/2010

Longitude:

Tags:

Description: 536 Crude Processing Unit; north plot edge.

Category: Site Photo

Latitude:

Date Taken: 5/18/2010

Longitude:

Tags:

Description: Aerial View of facility around location of incident.

Category: Aerial

Latitude:

Date Taken:

Longitude:

Tags:

9533354