Photo 21: Corroded Floor on Second Floor of Building 2

Photo 22: Drums (New and Used Product) on Second Floor of Building 5

Photo 23: Used Drum for the Storage of Waste Oil on Second Floor of Building 3

Photo 24: Close Up of Label on Used Oil Drum