Photographs for Norlite, LLC - VP1120

Media: RCRA

Photo Number 87
Disk Number 1
Photo Filename IMGP0087.JPG
Date/Time 3/17/2015 1:46:38 PM
Photographer Jackie Vega

Description Truck unloading bay

Photo Number 88
Disk Number 1
Photo Filename IMGP0088.JPG
Date/Time 3/17/2015 1:54:20 PM
Photographer Jackie Vega

Description Covered hazardous waste tanks 300, 400, 500, and 600

Photographs for Norlite, LLC - VP1120

Media: RCRA

Photo Number 89
Disk Number 2
Photo Filename IMGP0089.JPG
Date/Time 3/18/2015 10:39:56 AM
Photographer Jackie Vega

Description Three sample sizes (large from truck, medium from drum, vial is composite)

Photo Number 90
Disk Number 2
Photo Filename IMGP0090.JPG
Date/Time 3/18/2015 10:46:58 AM
Photographer Jackie Vega

Description Plastic hazardous waste accumulation container for discharge from the ICP machine used for wastewater

Photographs for Norlite, LLC - VP1120

Media: RCRA

Photo Number 91
Disk Number 2
Photo Filename IMGP0091.JPG
Date/Time 3/18/2015 10:47:06 AM
Photographer Jackie Vega

Description Accumulation container for sample residue from ICP machine that has been digested in acid

Photo Number 92
Disk Number 2
Photo Filename IMGP0092.JPG
Date/Time 3/18/2015 10:55:20 AM
Photographer Jackie Vega

Description Hazardous waste accumulation container of discharge from ICP machine used for fuels

Photographs for Norlite, LLC - VP1120

Media: RCRA

Photo Number 93
Disk Number 2
Photo Filename IMGP0093.JPG
Date/Time 3/18/2015 10:55:58 AM
Photographer Jackie Vega

Description Accumulation container for sample residue from ICP machine used for fuels

Photo Number 94
Disk Number 2
Photo Filename IMGP0094.JPG
Date/Time 3/18/2015 10:58:56 AM
Photographer Jackie Vega

Description Two accumulation containers of waste from mercury analyzer

Photographs for Norlite, LLC - VP1120

Media: RCRA

Photo Number 95
Disk Number 2
Photo Filename IMGP0095.JPG
Date/Time 3/18/2015 11:06:06 AM
Photographer Jackie Vega

Description Accumulation container of waste from specific gravity test

Photo Number 96
Disk Number 2
Photo Filename IMGP0096.JPG
Date/Time 3/18/2015 11:11:14 AM
Photographer Jackie Vega

Description Silver nitrate waste from halogen test

Photographs for Norlite, LLC - VP1120

Media: RCRA

Photo Number 97
Disk Number 2
Photo Filename IMGP0097.JPG
Date/Time 3/18/2015 11:18:06 AM
Photographer Jackie Vega

Description Sales samples accumulating in lab prior to being put in walk-in storage unit

Photo Number 98
Disk Number 2
Photo Filename IMGP0098.JPG
Date/Time 3/18/2015 11:20:56 AM
Photographer Jackie Vega

Description Two accumulation containers for TCLP wastes

Photographs for Norlite, LLC - VP1120

Media: RCRA

Photo Number 99
Disk Number 2
Photo Filename IMGP0099.JPG
Date/Time 3/18/2015 11:28:16 AM
Photographer Jackie Vega

Description Waste from PCB analysis labeled "flammable/corrosive liquid (methanol, hexane)"

Photo Number 100
Disk Number 2
Photo Filename IMGP0100.JPG
Date/Time 3/18/2015 11:29:58 AM
Photographer Jackie Vega

Description Waste from PCB analysis labeled "flammable/corrosive liquid (methanol, hexane)"

Photographs for Norlite, LLC - VP1120

Media: RCRA

Photo Number 101
Disk Number 2
Photo Filename IMGP0101.JPG
Date/Time 3/18/2015 11:41:52 AM
Photographer Jackie Vega

Description Walk-in cooler for laboratory waste storage

Photo Number 102
Disk Number 3
Photo Filename IMGP0102.JPG
Date/Time 3/19/2015 10:28:56 AM
Photographer Jackie Vega

Description Sample outfall 06A at wastewater treatment plant

Photographs for Norlite, LLC - VP1120

Media: RCRA

Photo Number 103
Disk Number 3
Photo Filename IMGP0103.JPG
Date/Time 3/19/2015 10:43:00 AM
Photographer Jackie Vega

Description Filter press in wastewater treatment plant

Photo Number 104
Disk Number 3
Photo Filename IMGP0104.JPG
Date/Time 3/19/2015 10:57:06 AM
Photographer Jackie Vega

Description Pile of oversized clinker where filter cake is added

Photographs for Norlite, LLC - VP1120

Media: RCRA

Photo Number 105
Disk Number 3
Photo Filename IMGP0105.JPG
Date/Time 3/19/2015 10:57:12 AM
Photographer Jackie Vega

Description Larger pile of clinker where smaller pile is added

Photo Number 106
Disk Number 3
Photo Filename IMGP0106.JPG
Date/Time 3/19/2015 11:28:24 AM
Photographer Jackie Vega

Description Drum processing building