FT BUCHANAN
DOL FUEL POINT
SAN JUAN P R
787-707-3560

MAY 1, 2012 11:16 AM

SYSTEM STATUS REPORT
- - - - - - - - - - - - -
ALL FUNCTIONS NORMAL

INVENTORY REPORT

T 1:DIESEL
VOLUME = 5362 GALS
ULLAGE = 4366 GALS
90% ULLAGE= 3393 GALS
HEIGHT = 49.55 INCHES
WATER VOL = 27 GALS
WATER = 1.58 INCHES
TEMP = 85.6 DEG F

T 2:MOGAS
VOLUME = 3272 GALS
ULLAGE = 6456 GALS
90% ULLAGE= 5483 GALS
HEIGHT = 34.49 INCHES
WATER VOL = 51 GALS
WATER = 2.30 INCHES
TEMP = 85.4 DEG F

* * * * * END * * * * *

FT BUCHANAN
DOL FUEL POINT
SAN JUAN P R
787-707-3560

MAY 1, 2012 11:16 AM

LEAK TEST REPORT

T 1:DIESEL
PROBE SERIAL NUM 745309

TEST STARTING TIME:
APR 22, 2012 9:00 PM

LEAK TEST RESULTS
GROSS TEST PASS

* * * * * END * * * * *

FT BUCHANAN
DOL FUEL POINT
SAN JUAN P R
787-707-3560

MAY 1, 2012 11:16 AM

LEAK TEST REPORT

T 2:MOGAS
PROBE SERIAL NUM 745307

TEST STARTING TIME:
APR 22, 2012 9:00 PM

LEAK TEST RESULTS
GROSS TEST PASS

* * * * * END * * * * *

FT BUCHANAN
DOL FUEL POINT
SAN JUAN P R
787-707-3560

MAY 1, 2012 11:16 AM

LEAK TEST REPORT

T 1:DIESEL
PROBE SERIAL NUM 745309

TEST STARTING TIME:
APR 22, 2012 9:00 PM

TEST LENGTH = 2.0 HRS
STRT VOLUME = 5458.0 GAL

LEAK TEST RESULTS
0.20 GAL/HR TEST PASS

* * * * * END * * * * *

FT BUCHANAN
DOL FUEL POINT
SAN JUAN P R
787-707-3560

MAY 1, 2012 11:16 AM

LEAK TEST REPORT

T 2:MOGAS
PROBE SERIAL NUM 745307

TEST STARTING TIME:
APR 22, 2012 9:00 PM

TEST LENGTH = 2.0 HRS
STRT VOLUME = 3322.2 GAL

LEAK TEST RESULTS
0.20 GAL/HR TEST PASS

* * * * * END * * * * *

FT BUCHANAN
DOL FUEL POINT
SAN JUAN P R
787-707-3560

MAY 1, 2012 11:16 AM

LIQUID STATUS
- - - - - - - - - - - - -
MAY 1, 2012 11:16 AM

L 1:STP DIESEL
SENSOR NORMAL

* * * * * END * * * * *

FT BUCHANAN
DOL FUEL POINT
SAN JUAN P R
787-707-3560

MAY 1, 2012 11:17 AM

LIQUID STATUS
- - - - - - - - - - - - -
MAY 1, 2012 11:17 AM

L 2:STP MO GAS
SENSOR NORMAL

* * * * * END * * * * *

FT BUCHANAN
DOL FUEL POINT
SAN JUAN P R
787-707-3560

MAY 1, 2012 11:17 AM

LIQUID STATUS
- - - - - - - - - - - - -
MAY 1, 2012 11:17 AM

L 3:BRAINE DIESEL
SENSOR NORMAL

* * * * * END * * * * *

FT BUCHANAN
DOL FUEL POINT
SAN JUAN P R
787-707-3560

MAY 1, 2012 11:17 AM

LIQUID STATUS
- - - - - - - - - - - - -
MAY 1, 2012 11:17 AM

L 4:BRAINE MOGAS
SENSOR NORMAL

* * * * * END * * * * *

FT BUCHANAN
DOL FUEL POINT
SAN JUAN P R
787-707-3560

MAY 1, 2012 11:14 AM

SYSTEM STATUS REPORT

ALL FUNCTIONS NORMAL

INVENTORY REPORT

T 1:DIESEL

VOLUME	=	5362	GALS
ULLAGE	=	4366	GALS
90% ULLAGE	=	3393	GALS
HEIGHT	=	49.55	INCHES
WATER VOL	=	27	GALS
WATER	=	1.58	INCHES
TEMP	=	85.6	DEG F

T 2:MOGAS

VOLUME	=	3272	GALS
ULLAGE	=	6456	GALS
90% ULLAGE	=	5483	GALS
HEIGHT	=	34.49	INCHES
WATER VOL	=	51	GALS
WATER	=	2.30	INCHES
TEMP	=	85.4	DEG F

* * * * * END * * * * *