Directorate of Public Works
Environmental Division
After Action Report

Subject: EPA Inspection to the 448th Consolidated Motor Pool USAR Center - Building 528, Fort Buchanan, PR on 25 April 2012.
Site: 448TH Consolidated Motor Pool – OMS, Building 528, Fort Buchanan, PR.
Date: April 30, 2012
For additional information, the appointed Technical POC is Ms. Addy Z. Molina Vazquez, Environmental Compliance Manager, telephone 787-707-2677, or email: addy.z.molina@us.army.mil.

Observation: The label of "Used Solvent" was replaced for "Used Solvent Part Washer"
A lid was place to keep the drum closed.

Diesel Fuel Storage Material Area (new material)
Three of 5 gallons of Diesel Fuel

Hazardous Waste Storage Area



Empty Drums

Used Rags

Flammable Storage Area: Paints, Aerosols and hand soap cleaners dispensers. (New Material)

Hand soap (Soy base)

Paints

Monthly Inventory Report

Petroleum, Oil and Lubricants (POLs) Storage Area: Grease, Oil and Transmission Fluids, Parts Washer Cleaners. (New Material)

Monthly Inventory Report