Table 1

Summary of Areas of Concern
McDonnell Douglas C-6 Facility

Area of Concern	Chemicals Analyzed for	Chemicals Detected	Number of Borings/Depth	Soil Impacted	Groundwater Impacted	Other	Reference
Tank 37T	BTEX	None	Soil samples beneath tank	Unknown	Unknown	130 gal diesel; located on the north side of building 1	KJC, 1996b
Tanks 15T, 16T, 17T, 18T						15T was 3,000 gallon waste solvent tank 16T - 18T were 5,000 gallon solvent storage tanks	KJC, 1996b
PCB oil spill next to building 61	? Assumably PCB or TRPH	PCB	Confirmation sampling	Remediated (excavated)	Not Likley	60 gal dielectric oil spilled; 15 cuyds excavated	KJC, 1996b
Western fence of parking lot	VOC Priority Pollutant metals PCBs Organo-chlorine pesticides	All below regulatory limits	3 to 31.5'	No	Unknown		KJC, 1996b
Hazardous Waste accumulation area between Builings 29 and 1	Total Cr, Hex Cr, Pb, Zn, and CN VOC (8020)	CN 1,2-DCA 1,1,1-TCA 1,1,1,2-PCA toluene	several locations 1' below concrete	Yes	Unknown		KJC, 1996b
Fuel tank in the roadway south of Building 29	Not sampled	Not sampled	None	Unknown	Unknown	1,000 gallon fuel tank noted in the roadway on the 1945 plant drawing.	KJC, 1996b
Butylene line beneath north end of Building 37						From as-built drwing dated May 22, 1968	KJC, 1996b

BOE-C6-0128895