HAZARDOUS WASTE LOG SHEET

PAGE: 2 OF 3 LOCATION: C6 TORRANCE MONTH: July YR: 1994

MANIFEST NO.	DATE MANIFESTED	TRANSPORTER	DAC TANK NO.	CONTENTS	QUANTITY	CAT. NO./ DOT CLASS	DATE MANIF. RTN.	TSDF	DISP METHOD	TAX CAT.	ACTUAL QUANTITY	DISPOSAL CHARGE	TRANSP. CHARGE	TOTAL CHARGE
85923 93385923 (Continued from page 1)			d) Primer Contaminated Debris 520573	d) RQ, Hazardous waste solid, n.o.s., 9, UN3077, PG III (D007)	001 DM 00085 P	352 D007	07-27-94							
			a) Sealant Tubes 520575	a) RQ, Hazardous waste Solid, n.o.s., 9 NA3077 PG III, (D007, D008)	001 DM 00070 P	352 D007, D008 9								
			b) Trich Rinse water Tank #81 520467	b) RQ, Hazardous waste, liquid, n.o.s., 9, NA3082, PG III (F001)	006 LM 02440 P	791 F001								
			c) Bulked trich from solvent cans 520468	c) waste 1,1,1-trichloroethane 6.1, UN2831, PG III	001 DM 00080 P	211 U226								
			d) Trich Solids Tank #81 520469	d) Hazardous waste, solid n.o.s. 9, NA 3077 PG III, (F001)	001 DM 245 P	352 F001								
			e) Tank 152 520470	e) RQ, waste combustible liquids, n.o.s., (Stoddard solvent) combustible liquids, NA 1993, PG III (D001)	001 DM 00235 P	214 D001								
85933 93385933	07/22/94	Laidlaw	Cut-up paint tables 12104-ITR004	RQ, Hazardous waste, Solid, n.o.s., 9 NA3077, PG III (D007)	001 CM 10360 P	352 D007	08/05/94	Laidlaw West Morland, CA						
85922 93385922	07/25/94	Laidlaw	a) Purge Water 110328-03	a) Hazardous waste, liquid, n.o.s., 9, NA3082, PG III (D022, D028)	019 DM 08350 P	134 D022, D028	08/12/94	Chem-Tech						
			b) Fluorescent Penetrant Oil 110909	b) Penetrant Oil Non-RCRA Hazardous Waste Liquid	012 DM 05000 P	223 N/R								
			c) Diesel and water 240705-01	c) Diesel and water Non-RCRA Hazardous Waste Liquid	003 DM 01200 P	213 N/R								
94268 93682538	07/26/94	Safety-Kleen Corp.	From Safety Kleen Tanks.	a) RQ, waste combustible liquid, N.O.S. (Petroleum Naptha) NA1993, PG III (D001, D006, D008, D018, D035, D039, D040)	004 DM 74 G	74 D006, D001, D008, D018, D035, D039, D040	07/28/94	Safety-Kleen Corp						
3158 NON-HAZ. Load #1 MPST	07/27/94	Maness Env. Services, Inc.	Excavation and removal of UST Tanks.	Non-Hazardous Soil	APROX 22 TONS (NOT WEIGHED AT DAC)	N/A	N/A	TPS Technologies Inc.						
3158 NON-HAZ Load #2 MPST	07/27/94	"	"	"	APPROX 22 TONS (NOT WEIGHED AT DAC)			"						
3158 NON HAZ LOAD #3 MPST	07/27/94	"	"	"	APPROX 22 TONS (NOT WEIGHED AT DAC)			"						
3158 NON-HAZ LOAD #4 MPST	07/27/94	"	"	"	APPROX 22 TONS (NOT WEIGHED AT DAC)			"						
3158 NON-HAZ LOAD #5 MPST	07/27/94	"	"	"	APPROX 22 TONS (NOT WEIGHED AT DAC)			"						
3158 NON HAZ LOAD #6 MPST	07/27/94	"	"	"	APPROX 22 TONS (NOT WEIGHED AT DAC)			"						
3158 NON HAZ LOAD #7 MPST	07/27/94	"	"	"	40,860 P			"						
3158 NON LOAD #8	07/27/94	"	"	"	42,800 P			"						

LOCATION: C6 MONTH: July YEAR: 1994

PAGE: 2 OF 3

DATE BLUE COPY MAILED TO DTSC			

BOE-C6-0207243