REPORT

TRUESDAIL LABORATORIES, INC.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS
RESEARCH — DEVELOPMENT — TESTING

14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
AREA CODE 714 • 730-6239
AREA CODE 213 • 225-1564
FAX 714 • 730-6462

CLIENT: **Douglas Aircraft Company**
Internal Mail Code 74-41
3855 Lakewood Boulevard
Long Beach, California 90846
Attention: Kathleen Faretta

DATE: July 13, 1990

RECEIVED: July 12, 1990

LABORATORY NO.: 37460

SAMPLE: **Storm Drain Inspection - First Quarter**
P.O. No.: T & M-23465-C

INVESTIGATION: **Analysis as requested by the CRWQCB for NPDES Permit Numbers CA0001406 and CA0001414**

RESULTS

A representative of Truesdail Laboratories, Inc., tested the storm drain discharge on July 12, 1990, at the Douglas Torrance Facility and Long Beach facility (003). The discharge was tested for flow rate, pH, and temperature. A grab sample was returned to the laboratory and analyzed according to the American Public Health Association's "Standard Methods," 17th Edition. The results are as follows:

Sample I.D.	Date	Time	Flow-gpd	Temp, °F	pH, units
Long Beach (003)	7/12/90	12:05	No flow	75	8.1
Torrance	7/12/90	11:00	590	70	7.4

	MILLIGRAMS PER LITER	
	Long Beach	Torrance
Settleable Solids, mls/liter (160.5)	<0.1	<0.1
Total Suspended Solids (160.2)	3	15
Oil and Grease (415.1)	97.8	5

Respectfully submitted,
TRUESDAIL LABORATORIES, INC.

Gregory W. Everett, Proj. Mgr.
Industrial Waste

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.