FIGURE 3



DIAGRAM OF SEWER SYSTEM WITHIN STUDY AREA

GREELEY AND HANSEN ENGINEERS

WESTCHESTER COUNTY, NEW YORK
YONKERS COMBINED SEWER OVERFLOW STUDY
AUGUST 1985