Jimenez, Jose

From: Lindsey, Deborah
Sent: Tuesday, August 13, 2013 1:34 PM
To: Kline, James
Subject: FW: Carter Impoundment - July 31, 2013 - Photos (A)
Attachments: Carter Impoundment - July 31, 2013 (3).JPG; Carter Impoundment - July 31, 2013 (130).JPG; Carter Impoundment - July 31, 2013 (22).JPG; Carter Impoundment - July 31, 2013 (124).JPG; Carter Impoundment - July 31, 2013 (16).JPG; Carter Impoundment - July 31, 2013 (135).JPG; Carter Impoundment - July 31, 2013 (9).JPG; Carter Impoundment - July 31, 2013 (88).JPG

Jim

These were the latest photos I received from the resident near the Carter Impoundment

---

From: Janet Lauff [mailto:[redacted]] Ex 6
Sent: Wednesday, July 31, 2013 6:10 PM
To: Lindsey, Deborah
Subject: FW: Carter Impoundment - July 31, 2013 - Photos (A)

From: Janet Lauff [mailto:[redacted]] Ex 6
Sent: Wednesday, July 31, 2013 5:49 PM
To: Janet Lauff
Subject: Carter Impoundment - July 31, 2013 - Photos

Photo #3 - The white tanker truck beside the Baker weir tanks is being used for power washing the liner (On the side of the white tanker it says Heritage 25-549)

Photo #130 - There is a green pump near the manifold pipes that appear to be pulling the water from the impoundment into the weir tanks.

Photo #22 – Residual Waste Trucks hooked up to the weir tanks.

Photo #124 - Water on access road that was sprayed by a Advanced Equipment tanker. He continued to spray as he crossed the stream... (I wasn't able to get back to the camera to video it)

Photo #16 – Looks like a pump

Photo #135 – Power washing the liner.

Photo #9 – Residual Waste trucks lined up on the Cowden Well Pad prior to entering the impoundment.

Photo #88 – Closer look at the silver canister