J. Austin Adams
Environmental Specialist – Air

MidContinent
Chevron North America
6301 Deauville Blvd
Midland, Tx 79706
Tel (432) 687-7852
Jonathan.Adams@Chevron.com

RECEIVED

OCT 31 2019

Enforcement and Compliance
Assurance Division

October 25, 2019

U.S. EPA Region 8
ATTN: Director, Air and Toxics Technical Enforcement Program
Office of Enforcement, Compliance and Environmental Justice
1595 Wynkoop Street
Denver, CO 80202-1129
(303) 312-6312

RE: NSPS OOOOa Annual Report

As per 40 CFR §60.5420a(b), please find attached the Annual Report for Chevron's NSPS OOOOa affected sites. This report is for the compliance period of August 2, 2018 to August 1, 2019.

If you have any questions concerning this submission, please contact me at (432) 687-7852 or by email at jonathan.adams@chevron.com.

Sincerely,

(b) (6) [redacted]

J. Austin Adams
Environmental Specialist – Air

(b) (6) [redacted]

CC: Colorado Department of Public Health & Environment
Air Pollution Control Division
4300 Cherry Creek Drive South
Denver, CO 80246

Chevron U.S.A. Inc.

NSPS OOOOa Annual Report

For the Reporting Period 8/2/2018 to 8/1/2019

Mailing Address

Chevron U.S.A. Inc.
c/o J. Austin Adams
6301 Deauville Blvd
Midland, TX 79706

For questions and comments, please contact:
J. Austin Adams
(432) 687-7852
jonathan.adams@Chevron.com

Statement of Certification: Based on information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate and complete.

Name of Certifying Official: Mr. Don Puckett

Title: General Manager Operations

Signature of Certifying Official: (b) (6) [redacted]

Signature Date: 10/23/2019

The following facilities/wells are NSPS OOOOa Affected Facilities pursuant to 40 CFR § 60.5420a(b)

Company Name	**Facility Site Name**	US Well ID	County	State	Latitude	Longitude
Chevron USA Inc	Skinner Ridge 25 BV	N/A	Garfield	CO	(b) (9) [redacted]	
Chevron USA Inc	Skinner Ridge 25CV	N/A	Garfield	CO		
Chevron USA Inc	Central Processing Facility	N/A	Garfield	CO		

Fugitive Emission Components : Monitoring Survey Information

60.5420(b)(7)(i)-(v) LDAR Survey data for the collection of fugitive emission components.

Facility Name	Date of Survey	Begin Time of Survey	End Time of Survey	Operator Name	Ambient Temperature	Sky Conditions	Wind Speed (mph)	Monitoring Instrument Used	Deviations From Monitoring Plan (If none, state none.) * (§60.5420a(b)(7)(vi))
Central Processing Facility	10/23/2018	12:27 PM	12:46 PM	(b) (6) [redacted]	48	Partly Cloudy	7	Optical Gas Imaging Camera	No Deviations
Skinner Ridge 25 BV	10/23/2018	9:03 AM	10:22 AM		48	Partly Cloudy	7	Optical Gas Imaging Camera	No Deviations
Skinner Ridge 25 CV	10/23/2018	11:11 AM	12:04 PM		48	Partly Cloudy	7	Optical Gas Imaging Camera	No Deviations
Central Processing Facility	3/21/2019	2:25 PM	3:21 PM		39	Sunny	13	Optical Gas Imaging Camera	No Deviations
Skinner Ridge 25 BV	4/23/2019	8:09 AM	9:46 AM		49	Sunny	4	Optical Gas Imaging Camera	No Deviations
Skinner Ridge 25 CV	4/23/2019	10:12 AM	11:39 AM		49	Sunny	4	Optical Gas Imaging Camera	No Deviations
Central Processing Facility	6/26/2019	10:55 AM	1:00 PM		73	Sunny	9	Optical Gas Imaging Camera	No Deviations