NWW No. 022201080
Photo No. 1
Lee Peterson, Water District No. 37 & 37M
Silver Creek, Blaine County, Idaho
Date: 04 September 2002
By: Robert Flowers
Description: Breach cut in dike between pond and culvert outlet

NWW No. 022201080
Photo No. 2
Lee Peterson, Water District No. 37 & 37M
Silver Creek, Blaine County, Idaho
Date: 04 September 2002
By: Robert Flowers
Description: Breach cut in dike between pond and culvert outlet

NWW No. 022201080
Photo No. 3
Lee Peterson, Water District No. 37 & 37M
Silver Creek, Blaine County, Idaho
Date: 04 September 2002
By: Robert Flowers
Description: Breach cut in dike between pond and culvert outlet

NWW No. 022201080
Photo No. 4
Lee Peterson, Water District No. 37 & 37M
Silver Creek, Blaine County, Idaho
Date: 04 September 2002
By: Robert Flowers
Description: Cross-section 1 - 1
Station No. 1+00

NWW No. 022201080
Photo No.5
Lee Peterson, Water District No. 37 & 37M
Silver Creek, Blaine County, Idaho
Date: 04 September 2002
By: Robert Flowers
Description: Cross-section 2 - 2
Station No. 1+29

NWW No. 022201080
Photo No.6
Lee Peterson, Water District No. 37 & 37M
Silver Creek, Blaine County, Idaho
Date: 04 September 2002
By: Robert Flowers
Description: Cross-section 3 - 3
Station No. 4+00

NWW No. 022201080
Photo No.7
Lee Peterson, Water District No. 37 & 37M
Silver Creek, Blaine County, Idaho
Date: 04 September 2002
By: Robert Flowers
Description: Cross-section 4 - 4
Station No. 6+00

NWW No. 022201080
Photo No.8
Lee Peterson, Water District No. 37 & 37M
Silver Creek, Blaine County, Idaho
Date: 04 September 2002
By: Robert Flowers
Description: Cross-section 5 - 5
Station No. 10+94

NWW No. 022201080
Photo No.9
Lee Peterson, Water District No. 37 & 37M
Silver Creek, Blaine County, Idaho
Date: 04 September 2002
By: Robert Flowers
Description: Fill in Silver Creek near Cross-section 5 - 5