Message

From: Leo Brausch [lbrausch@consolidated.net]
Sent: 4/17/2015 7:54:55 PM
To: Santos, Carmen [Santos.Carmen@epa.gov]
CC: 'Cepko, Russ P' [Russ.Cepko@cbs.com]; Rykaczewski, Dave A. [dave.rykaczewski@wspgroup.com]
Subject: Sampling and Analysis Results -- Former Westinghouse Apparatus Repair Plant, Rancho Dominguez, California.
Attachments: 1503577 Report.pdf; 1503605 Report.pdf; J48686-1 UDS Level 2 Report Final Report.pdf; J48849-1 UDS Level 2 Report Final Report.pdf; J48849-2 UDS Level 2 Report Final Report.pdf; J48892-1 UDS Level 2 Report Final Report.pdf; J48970-1 UDS Level 2 Report Final Report.pdf; J49230-2 UDS Level 2 Report Final Report.pdf; 00041949-D16-Figure 1.pdf; 00041949-D17-Figure 1.pdf; 00041949-D18-Figure 1.pdf

Carmen,

Attached for your information are the sampling and analysis results generated to date from the cleaning of the former Westinghouse Apparatus Repair facility in Rancho Dominguez, California. CBS and its contractors began the cleaning work on March 23, 2015, and we are approximately 40 percent complete. The following attached files provide preliminary (unvalidated) data for the bulk, wipe, and air samples collected and analyzed to date. The data are provided in the Level 2 data reports; wipe and bulk sample locations and results are shown on the attached drawings. Results are pending for sample locations shown without results.

Following are descriptions of the provided PDF files:

- 00041949-D16-Figure 1 – Locations and results of concrete floor chip samples;
- 00041949-D17-Figure 1 – Locations and results of wall samples, including non-porous (wipe) and porous (chip) samples;
- 00041949-D18-Figure 1 – Locations and results of wipe samples of non-porous surfaces;
- 1503577 Report and 1503605 Report – Analytical laboratory reports from ALS Environmental for baseline air samples; and
- J48686-1, J48849-1, J48849-2, J48892-1, J48970-1, and J49230-2 – Analytical laboratory reports from TestAmerica for wipe and bulk samples.

Please note that the drawings are oversized, and you need to zoom in on the PDF file versions to make the information readable.

WSP collected the baseline air samples during the week of March 16 and these data reports are also attached. Both PUF and quartz filter samples were collected and analyzed separately. The sample identifications for the air samples are not shown on the drawings, but descriptions are as follows:

- Sample 01 – Northeast portion of the warehouse;
- Sample 02 – Office area on the west side of the facility;
- Sample 03 – Outdoors on the north side of the facility;
- Sample 04 – Southwest portion of the warehouse;
- Sample 05 – Northwest portion of the warehouse;
- Sample 06 – Break room in the interior structure (central portion of warehouse);
- Sample 07 – Southeast portion of the warehouse; and
- Sample 200 – Duplicate of Sample 04

We continue to collect data as the cleaning work proceeds. We will forward another "package" of preliminary data as it becomes available. We will compile all of the final (validated) data into tables and figures as part of the report on this cleaning activity.

Please let us know if you have any questions at this time. Thanks.

Leo M. Brausch
Office: (724) 444-0377
Cell: (412) 720-8549
Fax: (724) 444-0351