

LEGEND

— — — — — —	PROPERTY LINE
~~	APPROXIMATE PHASE I EXCAVATION LIMITS
ESC-SB-125	SOIL BORING LOCATION DRILLED MARCH/DECEMBER 2005
SW8-1	PHASE I EXCAVATION CONFIRMATION SAMPLE JUNE 2007
UP1	PROPOSED SOIL BORING LOCATION

TPH1 = TPH C12 - C22
TPH2 = TPH C22 - C40
PCB1 = AROCLOR 1016
PCB2 = AROCLOR 1248
PCB3 = AROCLOR 1260
ND = NO PCBS DETECTED IN SIDEWALL SAMPLE

1	80	PCB2

SAMPLE DEPTH (FEET) — RESULT IN MG/KG — CONSTITUENT

*SOIL ANALYTICAL RESULTS FOR BORINGS WITHIN THE PHASE I REMEDIATION AREA WERE EXCLUDED BECAUSE ALL ELEVATED CONSTITUENTS IN THE SOIL WERE REMOVED BY EXCAVATION.

WSP ENVIRONMENT & ENERGY
2025 GATEWAY PLACE SUITE 435
SAN JOSE, CALIFORNIA 95110
(408) 453-6100

Figure 2
Proposed Soil Sample Locations
Former Westinghouse Equipment Repair Facility
Rancho Dominguez, California

45730680.DWG