11626 - 11678 SEMS-RM DOCID # 1166932

# UNDERGROUND STORAGE TANK UNAUTHORIZED RELEASE (LEAK) / CONTAMINATION SITE REPORT

EMERGENCY ☐ YES ☐ NO

HAS STATE OFFICE OF EMERGENCY SERVICES REPORT BEEN FILED ? ☐ YES ☐ NO

REPORT DATE M M D D Y Y

CASE #

FOR LOCAL AGENCY USE ONLY
I HEREBY CERTIFY THAT I AM A DESIGNATED GOVERNMENT EMPLOYEE AND THAT I HAVE REPORTED THIS INFORMATION TO LOCAL OFFICIALS PURSUANT TO SECTION 25180.7 OF THE HEALTH AND SAFTY CODE.

SIGNED John Awujo DATE 11/28/06

**REPORTED BY**

NAME OF INDIVIDUAL FILING REPORT: John Awujo
PHONE: (626) 458 3507
SIGNATURE: John Awujo

REPRESENTING: ☐ OWNER/OPERATOR ☐ REGIONAL BOARD ☒ LOCAL AGENCY ☐ OTHER
COMPANY OR AGENCY NAME: Los Angeles County Public Works

ADDRESS: 900 South Fremont Ave. Alhambra CA 91803
STREET CITY STATE ZIP

**RESPONSIBLE PARTY**

NAME: Shultz Steel Company ☐ UNKNOWN
CONTACT PERSON: Peter Nash
PHONE: (323) 564 3281

ADDRESS: 5321 Firestone Blvd. South Gate CA 90280
STREET CITY STATE ZIP

**SITE LOCATION**

FACILITY NAME (IF APPLICABLE): Shultz Steel Company
OPERATOR: Peter Nash
PHONE: (323) 564 3281

ADDRESS: 5321 East Firestone Blvd. South Gate LA 90280
STREET CITY COUNTY ZIP

CROSS STREET: Rayo Avenue

**IMPLEMENTING AGENCIES**

LOCAL AGENCY / AGENCY NAME: L.A County Public Works
CONTACT PERSON: Tim Smith
PHONE: (626) 458 3511

REGIONAL BOARD: CRWQCB
Yue Rong
PHONE: (213) 576 6710

**SUBSTANCES INVOLVED**

(1) NAME: TPH of 5000 ppm, BTEX; 26/33/20/590 ppm
QUANTITY LOST (GALLONS): ☐ UNKNOWN

(2) BTEX; .63/1.1/.62/1.7 ppm, MTBE of 10 ppm, 45 ppm, 17 ppm ☐ UNKNOWN

**DISCOVERY/ABATEMENT**

DATE DISCOVERED: 12 22 99
HOW DISCOVERED: ☐ TANK TEST ☐ INVENTORY CONTROL ☐ TANK REMOVAL ☐ SUBSURFACE MONITORING ☒ OTHER site assessment ☐ NUISANCE CONDITIONS

DATE DISCHARGE BEGAN: M M D D Y Y ☒ UNKNOWN

HAS DISCHARGE BEEN STOPPED ? ☐ YES ☐ NO IF YES, DATE M M D D Y Y

METHOD USED TO STOP DISCHARGE (CHECK ALL THAT APPLY): ☐ REMOVE CONTENTS ☐ REPLACE TANK ☒ CLOSE TANK ☐ REPAIR TANK ☐ REPAIR PIPING ☐ CHANGE PROCEDURE ☐ OTHER

**SOURCE/CAUSE**

SOURCE OF DISCHARGE: ☐ TANK LEAK ☐ UNKNOWN ☒ PIPING LEAK ☐ OTHER

CAUSE(S): ☐ OVERFILL ☐ RUPTURE/FAILURE ☐ SPILL ☐ CORROSION ☐ UNKNOWN ☐ OTHER

**CASE TYPE**

CHECK ONE ONLY: ☐ UNDETERMINED ☐ SOIL ONLY ☒ GROUNDWATER ☐ DRINKING WATER - (CHECK ONLY IF WATER WELLS HAVE ACTUALLY BEEN AFFECTED)

**CURRENT STATUS**

CHECK ONE ONLY: ☐ NO ACTION TAKEN ☒ LEAK BEING CONFIRMED ☐ REMEDIATION PLAN ☐ PRELIMINARY SITE ASSESSMENT WORKPLAN SUBMITTED ☐ PRELIMINARY SITE ASSESSMENT UNDERWAY ☐ CASE CLOSED (CLEANUP COMPLETED OR UNNECESSARY) ☐ POLLUTION CHARACTERIZATION ☐ POST CLEANUP MONITORING IN PROGRESS ☐ CLEANUP UNDERWAY

**REMEDIAL ACTION**

CHECK APPROPRIATE ACTION(S) (SEE BACK FOR DETAILS): ☐ CAP SITE (CD) ☐ CONTAINMENT BARRIER (CB) ☐ VACUUM EXTRACT (VE) ☐ EXCAVATE & DISPOSE (ED) ☐ EXCAVATE & TREAT (ET) ☐ NO ACTION REQUIRED (NA) ☒ OTHER (OT) Not specified ☐ REMOVE FREE PRODUCT (FP) ☐ PUMP & TREAT GROUNDWATER (GT) ☐ TREATMENT AT HOOKUP (HU) ☐ ENHANCED BIO DEGRADATION (IT) ☐ REPLACE SUPPLY (RS) ☐ VENT SOIL (VS)

**COMMENTS**

MTBE of 10 ppm, 45 ppm; 17 ppm, 77 ppm, 35 ppm, 68 ppm
Groundwater impact

C505036

HSC 05 (11/00)