Table 1. Summary of Total Equipment Monitored and Leaks Detected, Equipment in Benzene Service, July 1999 through December 2000, USS Clairton Works, Clairton, Pennsylvania

		Jul	Aug	Sep	Oct	Nov	Dec
Monitoring Dates		21ST/22ND	26th	22ND	27th/28th	18th/24th	22nd
Total Components Monitored		*2197*	*209*	*25*	*2784*	*21*	*21*
Valves	Components Monitored	2179	191	4	2763	0	0
	Leaks Detected	5	1	0	0	0	0
	Percent Leakers			0.25%			0.00%
	Components Not Repaired in 5/15 Period	0	0	0	0	0	0
	Components Requiring Delay of Repair	0	0	0	0	0	0
Pumps/ Agitators	Components Monitored	18	18	21	21	21	21
	Leaks Detected	0	0	0	0	0	0
	Percent Leakers			0.00%			0.00%
	Components Not Repaired in 5/15 Period	0	0	0	0	0	0
	Components Requiring Delay of Repair	0	0	0	0	0	0
Other / Connectors	Components Monitored	0	0	0	0	0	0
	Leaks Detected	0	0	0	0	0	0
	Percent Leakers			0.00%			0.00%
	Components Not Repaired in 5/15 Period	0	0	0	0	0	0
	Components Requiring Delay of Repair	0	0	0	0	0	0

ED_002508A_00001306-00001