CWF Part 2 Hearing

Rebuttal Testimony

SDWA-323-Revised
Errata Dated 8-16-2018

8 revised Pages



Figure 1 Location of the Central Delta Salinity Analysis Points (8-16-2018 Errata)

Figure 2 Location of the South Delta Salinity Analysis Points (8-16-2018 Errata)



Figure 8 Location of Surveyed Cross-Sections on Middle River.



Figure 9 Comparison of DSM2 Geometry at Middle River Cross-Section MR-1 (8-16-18 Errata)



Figure 10 Comparison of DSM2 Geometry at Middle River Cross-Section MR-2 (8-16-18 Errata)



Figure 11 Comparison of DSM2 Geometry at Middle River Cross-Section MR-7 (8-16-18 Errata)



Figure 15 Old River Cross-Section; Site OR-1 (8-16-2018 Errata)



Figure 16 Old River Cross-Section; Site OR-2 (8-16-2018 Errata)



Figure 17 Old River Cross-Section; Site OR-3 (8-16-2018 Errata)



Figure 18 Old River Cross-Section; Site OR-4 (8-16-2018 Errata)



Figure 19 Old River Cross-Section; Site OR-5 (8-16-2018 Errata)



Figure 20 Old River Cross-Section; Site OR-6 (8-16-2018 Errata)



Figure 21 Old River Cross-Section; Site SUG-2 (8-16-2018 Errata)



Figure 22 Old River Cross-Section; Site SUG-1 (8-16-2018 Errata)