Please complete every section daily and give to at ENV Station 001.

Date: Aug. 8, 2017
Time: 12:56 p.m.
Initials: TRB

Outfall 009/010	Answers
Substance discharged? Foam	(Y) / N
-If Yes, Color?	White not oil
-If Yes, Size / Area?	10'x2'
Vac truck amount recovered	250 Gallons water Foam
Estimated oil recovered	0
Length of sorbent boom replaced	250' of area Sock boom
Canal Appearance (winds, sheen, etc.)	Calm

* picked up by National. Reported to IDEM under NPDES Narrative Standard using 24hr. Form.

Date: Aug. 8, 2017
Time: 6:26 a.m.
Initials: TRB

Outfall 001	Answers
Substance discharged?	Y / (N)
-If Yes, Color?	—
-If Yes, Size / Area?	—
Vac truck amount recovered	250 Gallons
Estimated oil recovered	~3 Gall.
Length of sorbent boom replaced	25' (inside weir area)
Canal Appearance (winds, sheen, etc.)	Calm