Message

From: Chapman, Apple [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=C52A18BCF6164B6D9F04545DB694CAC1-ACHAPMAN]
Sent: 6/11/2019 1:53:27 PM
To: NMENV Kenney James [James.Kenney@state.nm.us]
Subject: Fwd: EPA/NMED COG Inspections in Southeastern New Mexico
Attachments: InspRptAirCOG-NMPermianBasin20190419.pdf; ATT00001.htm

Sent from my iPhone

Begin forwarded message:

From: "Thompson, Steve" <thompson.steve@epa.gov>
To: "Seager, Cheryl" <Seager.Cheryl@epa.gov>, "Chapman, Apple" <Chapman.Apple@epa.gov>
Subject: FW: EPA/NMED COG Inspections in Southeastern New Mexico

Email sent

Steve Thompson
Branch Chief
Air Enforcement Branch
Enforcement and Compliance Assurance Division
U.S. EPA Region 6
Dallas,TX 75202
214-665-2769
thompson.steve@epa.gov

From: Thompson, Steve
Sent: Monday, June 10, 2019 3:39 PM
To: jknowlton@concho.com
Cc: Larson, Darrin <Larson.Darrin@epa.gov>; Kuehn, Elizabeth, NMENV <Elizabeth.Kuehn@state.nm.us>
Subject: EPA/NMED COG Inspections in Southeastern New Mexico

Ms. Knowlton,

The United States Environmental Protection Agency (EPA) and the New Mexico Environmental Department (NMED) conducted partial Clean Air Act (CAA) compliance inspections at several COG facilities located in southeastern New Mexico on April 16 and April 17, 2019. Please note that the inspection report that was sent to you via email by Ms. Cynthia Kaleri on June 3, 2019 (also attached) is not final. The inspection report had not completed the interagency consultation and review process. EPA and NMED may have additional compliance concerns regarding COG's operations at these sites and others in New Mexico. The draft inspection report provided to you represented the observations of the EPA and NMED inspectors focusing on a limited set of compliance issues and did not constitute a formal determination of compliance with all federal and state requirements. Please don't hesitate to contact me if you have any specific questions.

Thank you,

Steve Thompson

Steve Thompson
Branch Chief
Air Enforcement Branch
Enforcement and Compliance Assurance Division
U.S. EPA Region 6
Dallas,TX 75202
214-665-2769
thompson.steve@epa.gov

From: Kaleri, Cynthia
Sent: Monday, June 03, 2019 1:39 PM
To: Jennifer Knowlton <jknowlton@concho.com>
Cc: Andrew Ahr <Andrew.Ahr@state.nm.us>; Nfodzo, Prince <Nfodzo.Prince@epa.gov>; Larson, Darrin <Larson.Darrin@epa.gov>; Williams, Christopher <Williams.Christopher@epa.gov>
Subject: CAA Compliance Evaluation Inspection at Multiple COG Facilities Located in Southeastern New Mexico

Hello Jennifer,

As you know, the United States Environmental Protection Agency (EPA) and the New Mexico Environmental Department (NMED) conducted partial Clean Air Act (CAA) compliance inspections at several COG facilities located in southeastern New Mexico on April 16 and April 17, 2019. A copy of the inspection report that covers those site visited is attached to this email for your review. EPA will use this report to determine COG's compliance with the CAA. Please review the report and let me know if you find any inaccuracies that may need correction. The attached inspection report will be posted to EPA's public website 10 days from the date of this email.

If you have any questions about this inspection report, please feel free to contact me directly at the number listed below. Thank you again, for the cooperation extended to EPA and NMED personnel while at these facilities.

Cynthia J. Kaleri
CAA Enforcement Officer
EPA Region 6

Phone (214) 665-6772
Mailing Address
Attention: Cynthia J. Kaleri (ECDAP)
United States Environmental Protection Agency
1445 Ross Avenue
Dallas, TX 75202-2733

This email may contain material that is** confidential, privileged, **and/or** attorney work product **and is for the sole use of the intended recipient. Any review, reliance or distribution by others or forwarding without express permission is strictly prohibited. If you are not the intended recipient, please contact the sender and delete all copies.