Note: Soil sample MW-1-6-6.0-8.0 was also analyzed for VOCs, SVOCs, TPH, and PCBs with no detections reported

Summary of organic compound (VOCs, SVOCs, TPH, and PCBs) detections in Soil Samples Collected from Phase 1 Monitoring Well Locations.

Lane Plating Works, Inc. Superfund Site
Dallas, Dallas County, Texas

Imagery Source: Texas Orthoimag
Program 2015 0.5 Meter DOQQ,
Texas Strategic Mapping Program

2019-03-08 M:\Federal\EPA\RAC II\0169-Lane RI-FS_309\GIS\MXDs\SAP\A1_Sap_LP_GW.mxd EA\Dallas jschwentz