


**Second Floor**
**105 Kisco Avenue Mount Kisco (C003)**




**Ground Floor**
**105 Kisco Avenue Mount Kisco (C003)**




**Warehouse-2**




**Warehouse-1**

**Legend**

- Radon Sample Location
- Exteriror Wall
- Interior Wall
- Entry door
- H - HVAC Unit
- W - Water Heater
- Stairs

| | | |
|---|---|---|
| SR - Showroom | DY - Display | |
| OF - Office | CT - Closet | |
| RM - Room | RA - Receiving Area | |
| LY - Lobby | BR - Bathroom | |
| RC - Reception | ER - Electrical Room | |
| ST - Storage | CR - Conference Room | |

**Weston Solutions, Inc.**

In Association with Scientific and Environmental Associates, Inc, Environmental Consultants, Inc., Avatar Environmental, LLC, On-Site Environmental, Inc, and Soveriegn Consulting, Inc.

**Figure 2D:**
**C003 Post-Remedial Radon Analytical Results Map**

Canadian Radium and Uranium Site
Mount. Kisco, New York

U.S. ENVIRONMENTAL PROTECTION AGENCY
Removal Support Team 3
CONTRACT # EP-S2-13-01

Notes:
Radon sampling was conducted using charcoal canisters.
Radon analytical results are reported in pico curies per liter (pCi/L).

| | |
|---|---|
| EPA OSC: | E. DALY |
| RST SPM: | B. NWOSU |
| PROJECT #: | 30400.021.006.2053 |