

First Floor
105 Kisco Avenue Mount Kisco (C003)



Ground Floor
105 Kisco Avenue Mount Kisco (C003)





Legend

- Radon Sample Location
- Exteriror Wall
- Interior Wall
- Entry door
- HVAC Unit
- Water Heater
- Stairs

SR	- Showroom	D	- Display		
OF	- Office	NA	- No Access		
RM	- Room	RA	- Receiving Area		
LY	- Lobby	UR	- Utilities Room		
RC	- Reception	EU	- Electrical Room		
ST	- Storage	CR	- Conference Room		

Weston Solutions, Inc.

In Association with Scientific and Environmental Associates, Inc, Environmental Consultants, Inc., Avatar Environmental, LLC, On-Site Environmental, Inc, and Soveriegn Consulting, Inc.

Figure 6C:
C003 Radon Analytical Results Map

Canadian Radium and Uranium Site
Mount. Kisco, New York

U.S. ENVIRONMENTAL PROTECTION AGENCY
Removal Support Team 3
CONTRACT # EP-S2-13-01

Notes:
Radon sampling was conducted using charcoal canisters
Radon analytical results are reported in pico curies per liter (pCi/L)

EPA OSC:	E. DALY
RST SPM:	B. NWOSU
PROJECT #:	30400.021.006.2053