

First Floor
105 Kisco Avenue, Mount Kisco (C003)



Warehouse-2



Ground Floor
105 Kisco Avenue, Mount Kisco (C003)



Warehouse-1

Legend

- Gamma Survey Location
- Exteriror Wall
- Interior Wall
- Entry door
- H - HVAC Unit
- W - Water Heater
- Stairs

SR - Showroom
OF - Office
RM - Room
LY - Lobby
RC - Reception
ST - Storage
D - Display
NA - No Access
RA - Receiving Area
UR - Utilities Room
EU - Electrical Room
CR - Conference Room

Weston Solutions, Inc.

In Association with Scientific and Environmental Associates, Inc, Environmental Consultants, Inc., Avatar Environmental, LLC, On-Site Environmental, Inc, and Soveriegn Consulting, Inc.

Figure 3:
C003 Indoor Gamma (FPIC) Survey Map

Canadian Radium and Uranium Site
Mount. Kisco, New York

U.S. ENVIRONMENTAL PROTECTION AGENCY
Removal Support Team 3
CONTRACT # EP-S2-13-01

Notes:
Radon sampling was conducted using charcoal canisters
Radon analytical results are reported in pico curies per liter (pCi/L)

EPA OSC:	E. DALY
RST SPM:	B. NWOSU
PROJECT #:	30400.021.006.2053