To: R5CERCLA.ROC[R5CERCLA.ROC@epa.gov]
Cc: Wagner, Christine[Wagner.Christine@epa.gov]
From: Nonresponsive based on revised scope @erllc.com]
Sent: Mon 7/19/2021 8:23:02 PM (UTC)
Subject: CERCLA Compliance Check Request

William,
I would like to check the CERCLA status of the following facility:
US Ecology Wayne Disposal, Inc
49350 North I-94 Service Dr
Belleville, MI 48111
EPA ID# MID048090633

This request is in support of EPA Region 3 Shiloh Church Road site in Nathalie, VA. The site ID# A38Q and the OSC is Christine Wagner who is copied on this email. We would like to send approximately 250 tons of VOC contaminated soil & debris to the above facility.
If you need any additional information, please let me know

Thanks

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.