EP713 **LAFAYETTE HIGH SCHOOL - BROOKLYN K400** **NY AST** **1000547927**
NNW **2630 BENSON AVENUE** **NY Spills** **N/A**
> 1 **BROOKLYN, NY 11214**
1.009 mi.
5330 ft. **Site 1 of 2 in cluster EP**

Relative:
Higher

Actual:
9 ft.

AST:

Name:	LAFAYETTE HIGH SCHOOL - BROOKLYN K400
Address:	2630 BENSON AVENUE
City,State,Zip:	BROOKLYN, NY 11214
Region:	STATE
DEC Region:	2
Site Status:	Unregulated/Closed
Facility Id:	2-355461
Program Type:	PBS
UTM X:	585818.12553
UTM Y:	4494204.99995
Expiration Date:	N/A
Site Type:	School

Affiliation Records:

Site Id:	17717
Affiliation Type:	Facility Owner
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	Not reported
Address1:	44-36 VERNON BOULEVARD
Address2:	Not reported
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	Not reported
Fax Number:	Not reported
Modified By:	MFLEONAR
Date Last Modified:	2017-06-08

Site Id:	17717
Affiliation Type:	Mail Contact
Company Name:	NYC DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	MUNENDRA SHARMA
Address1:	FIELD OPERATIONS-FUEL DIVISION
Address2:	44-36 VERNON BOULEVARD
City:	LONG ISLAND CITY
State:	NY
Zip Code:	11101
Country Code:	001
Phone:	(718) 349-5752
EMail:	MSHARMA@SCHOOLS.NYC.GOV
Fax Number:	Not reported
Modified By:	JSMACRI
Date Last Modified:	2019-08-13

Site Id:	17717
Affiliation Type:	Facility Operator
Company Name:	LAFAYETTE HIGH SCHOOL - BROOKLYN K400
Contact Type:	Not reported
Contact Name:	PLANT OPERATIONS

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(718) 349-5400
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NRLOMBAR
Date Last Modified:	2012-12-26

Site Id:	17717
Affiliation Type:	Emergency Contact
Company Name:	NEW YORK CITY DEPARTMENT OF EDUCATION
Contact Type:	Not reported
Contact Name:	SCHOOL SAFETY
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 935-3300
EMail:	Not reported
Fax Number:	Not reported
Modified By:	GDBREEN
Date Last Modified:	2014-09-10

Tank Info:

Tank Number:	001
Tank Id:	34663
Material Code:	0003
Common Name of Substance:	#6 Fuel Oil (On-Site Consumption)

Equipment Records:

	H00 - Tank Leak Detection - None
	A00 - Tank Internal Protection - None
	D01 - Pipe Type - Steel/Carbon Steel/Iron
	K00 - Spill Prevention - None
	B00 - Tank External Protection - None
	E02 - Piping Secondary Containment - Vault (with Access)
	F00 - Pipe External Protection - None
	I04 - Overfill - Product Level Gauge (A/G)
	J00 - Dispenser - None
	G02 - Tank Secondary Containment - Vault (w/access)
	C02 - Pipe Location - Underground/On-ground
	L00 - Piping Leak Detection - None
Tank Location:	Aboveground in subterranean vault with access for inspections.....
	Tank in subterranean vault but accessible for inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	01/01/1998
Capacity Gallons:	18000
Tightness Test Method:	NN
Date Test:	Not reported

Next Test Date:	Not reported
Date Tank Closed:	12/01/2010
Register:	True
Modified By:	NRLOMBAR
Last Modified:	04/14/2017
Material Name:	#6 fuel oil (on-site consumption)

SPILLS:

Name:	SPILL NUMBER 0210714
Address:	2630 BENSON AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0210714 / 2003-11-20
Facility ID:	0210714
Facility Type:	ER
DER Facility ID:	116777
Site ID:	203935
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2003-01-25
Investigator:	JBVOUGHT
Referred To:	Not reported
Reported to Dept:	2003-01-25
CID:	199
Water Affected:	Not reported
Spill Source:	Commercial/Industrial
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2003-01-25
Spill Record Last Update:	2003-11-20
Spiller Name:	Not reported
Spiller Company:	METRO FUEL
Spiller Address:	500 KINGSLAND AV
Spiller Company:	001
Contact Name:	SCOTT ALNWICK
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was VOUGHT Sangesland on desk duty: 1/25/2003 - Saturday morning fuel delivery at Lafyette High School in Brooklyn. Vought spoke with Joanne at Metro Fuel (718-383-1400)- 20 Gal spill occurred near fill, speedy dry used, no sewers or drains Contact: School Custodian 718-372-7414 1/27/2003 - Sangesland spoke with school custodian - He said Metro did an initial cleanup and scooped up a top layer of contaminated soil. Scott Alnwick of Metro Fuel was called again. He said Metro would return to the school on 1/28 or 1/29 to finish cleanup. Metro can not work on the site today (1/27) because of new snow on the ground (?). 11/20/2003-Vought-See spill #0111171 at same location. This spill closed by Vought."
Remarks:	"fitting came off out of fill box - all materal confined to sidewalk - speedy dry applied and all materal will be cleaned up"

All Materials:

Site ID:	203935
Operable Unit ID:	861828

Operable Unit:	01
Material ID:	514093
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	LAFAYETTE HIGH SCHOOL
Address:	2630 BENSON AVENUE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	0111171 / 2003-12-08
Facility ID:	0111171
Facility Type:	ER
DER Facility ID:	116777
Site ID:	136465
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C3
SWIS:	2401
Spill Date:	2002-02-25
Investigator:	MXTIPPLE
Referred To:	Not reported
Reported to Dept:	2002-02-25
CID:	266
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	2002-02-25
Spill Record Last Update:	2003-12-08
Spiller Name:	Not reported
Spiller Company:	NEW YORK CITY BOARD OF ED
Spiller Address:	28-11 QUEENS PLAZA NORTH
Spiller Company:	001
Contact Name:	Not reported
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was TIPPLE 02/25/2002 SITE VISIT REVEALED APPROXIMATELY 100 GAL OF #6 OIL COVERING A WALKWAY, GRASS AREA AND COATING THE BUILDING TO A HEIGHT OF NEARLY 20' NEAR THE FILL PORT. PETROLEUM TANK CLEANERS WERE ON SCENE CLEANING. 12/8/03 CLOSED BY TIPPLE//CLEANED ON 02"
Remarks:	"PROBLEM WITH THE FILL FITTING. HOSE CAME OFF DURING FILLING. SPILLED ONTO PAVED ALLEYWAY. BEING CLEANED UP. REPRESENTATIVE FROM NEW YORK CITY BOARD OF EDUCATION WAS NOTIFIED TO MAKE REPAIRS. UPDATE - WILLIAM ESTELL FROM BOARD OF EDUCATION CALLED TO MAKE SURE SPILL REPORTED, ALSO STATES AMOUNT OF PRODUCT SPILLED IS APPROX 100 GALLONS. 09:41 #198."

All Materials:

Site ID:	136465
Operable Unit ID:	848251

Operable Unit:	01
Material ID:	528765
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	20.00
Units:	G
Recovered:	20.00
Oxygenate:	Not reported

Name:	LAFAYETTE HIGH SCHOOL
Address:	2630 BENSON AVE
City,State,Zip:	BROOKLYN, NY 11214
Spill Number/Closed Date:	0712257 / 2011-08-16
Facility ID:	0712257
Facility Type:	ER
DER Facility ID:	343430
Site ID:	393850
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2008-02-21
Investigator:	SFRAHMAN
Referred To:	Not reported
Reported to Dept:	2008-02-21
CID:	444
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	Not reported
Remediation Phase:	0
Date Entered In Computer:	2008-02-21
Spill Record Last Update:	2011-08-16
Spiller Name:	ARJUN PATNEY
Spiller Company:	LAFAYETTE HIGH SCHOOL
Spiller Address:	2630 BENSON AVE
Spiller Company:	001
Contact Name:	ARJUN PATNEY
DEC Memo:	"2/21/08 - Raphael Ketani. I spoke to Arjun Patney of TRC (the SCA's consultants) (718) 752-5039. He said that they are doing a fuel management system upgrade and, as part of the process, they did soil borings. The borings encountered oil contaminated soil below the tank. I told them that DEC wanted all of the contamination removed. He said that the plan is either to abandon the tank in place or remove it. I asked him who was the contact at the SCA. He said that it was Lee Gutterman, Assistant Director, Industrial Hygiene Division, SCA, 3030 Thompson Avenue, LIC, 11101. I sent a CSL to Ms. Gutterman. ********** PBS:2-355461********** 03/06/08 Spoke with Arjun Patney, soil and ground water contamination near the UST.(sr) 03/10/08 Site meeting with Arjun Patney,DVIRKA and Bartilucci Consulting Engineers this morning.UST outside of the boiler room.No

soil contamination observed during the borings, light sheen on water at north side of the tank.Contractor will uncover the tank,clean it and remove any contaminated soil.If free product found in ground water, further investigation and remediation options will be discussed.(sr) 08/26/09 Called Arjun Patney today.Probably,he is not with SCA.Mr. Sean Clyne @(718)472-8516 is the person who handles the case now, he is out today.(sr) 08/12/10 UST investigation Summary Report in edocs.Eleven soil borings were advanced around the UST.Sixteen soil samples and three ground water samples were taken for lab analyses.The lab analytical results revealed petroleum

related SVOCs in soil and ground water slightly above the RSCOs and ground water standard/guidance values.The 20,000 gallon UST is to be permanently closed as part of a boiler replacement project at the school.Tank located approx 5 ft from the edge of the four story building and is encased in concrete.(sr) Soil and ground water analytical data indicate low level of SVOC present at the site. Therefore, I am closing the spill.(sr)"

Remarks: "UST IS LEAKING AND FOUND BY DOING BORINGS"

All Materials:

Site ID:	393850
Operable Unit ID:	1150801
Operable Unit:	01
Material ID:	2141442
Material Code:	0003A
Material Name:	#6 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Name:	LAFAYETTE HIGH SCHOOL
Address:	2630 BENSON AVE
City,State,Zip:	BROOKLYN, NY
Spill Number/Closed Date:	1213087 / 2013-01-03
Facility ID:	1213087
Facility Type:	ER
DER Facility ID:	431594
Site ID:	476258
DEC Region:	2
Spill Cause:	Equipment Failure
Spill Class:	C4
SWIS:	2401
Spill Date:	2012-12-06
Investigator:	SMSANGES
Referred To:	Not reported
Reported to Dept:	2012-12-06
CID:	Not reported
Water Affected:	Not reported
Spill Source:	Institutional, Educational, Gov., Other
Spill Notifier:	Other
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0

Date Entered In Computer:	2012-12-06
Spill Record Last Update:	2013-01-03
Spiller Name:	Not reported
Spiller Company:	SCHOOL
Spiller Address:	Not reported
Spiller Company:	999
Contact Name:	ROSARIO NICCHI
DEC Memo:	"Sangesland spoke to Mike Tumtley at STV Incorp. He said Lafayette High School was damaged by Hurricane Sandy in Oct 2012. A temp Boiler & tank was set up on a tractor trailer in a teacher's parking lot. A malfunction occurred in the boiler and oil leaked out of the trailer. School custodian dumped sand to keep the spilled oil contained. Boiler company did the cleanup that same day. No soil was impacted (all remained on paved teachers parking lot). Cleanup was completed. SCA is reviewing the closure report. "
Remarks:	"Clean up ongoing. Boiler company doing clean up. To asphalt and pavement"

All Materials:

Site ID:	476258
Operable Unit ID:	1226089
Operable Unit:	01
Material ID:	2223456
Material Code:	0001A
Material Name:	#2 fuel oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	75.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported