H67 West 1/8-1/4 0.152 mi. 803 ft. | **1956 LLC DBA TOMAT FLEET SERVICE**
2765 STILLWELL AVE
BROOKLYN, NY 11224

Site 3 of 3 in cluster H

NY AST | **A100298753**
N/A

Relative: Higher

Actual: 1 ft.

AST:

Name:	1956 LLC DBA TOMAT FLEET SERVICE
Address:	2765 STILLWELL AVE
City,State,Zip:	BROOKLYN, NY 11224
Region:	STATE
DEC Region:	2
Site Status:	Active
Facility Id:	2-610319
Program Type:	PBS
UTM X:	586165.68913
UTM Y:	4492640.06269
Expiration Date:	09/01/2020
Site Type:	Auto Service/Repair (No Gasoline Sales)

Affiliation Records:

Site Id:	369605
Affiliation Type:	Mail Contact
Company Name:	TOMAT FLEET SERVICE
Contact Type:	Not reported
Contact Name:	JOE ROZZI
Address1:	2765 STILLWELL AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11224
Country Code:	001
Phone:	(347) 587-6607
EMail:	TOMAT@VERIZON.NET
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-12-15

Site Id:	369605
Affiliation Type:	Facility Operator
Company Name:	1956 LLC DBA TOMAT FLEET SERVICE
Contact Type:	Not reported
Contact Name:	AL RAPISARDA
Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	001
Phone:	(347) 587-6607
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-12-15

Site Id:	369605
Affiliation Type:	Emergency Contact
Company Name:	STILLWELL GARAGE LLC AND NAMREBO INC
Contact Type:	Not reported
Contact Name:	AL RAPISARDA

Address1:	Not reported
Address2:	Not reported
City:	Not reported
State:	NN
Zip Code:	Not reported
Country Code:	999
Phone:	(718) 645-1000
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-12-15

Site Id:	369605
Affiliation Type:	Facility Owner
Company Name:	STILLWELL GARAGE LLC AND NAMREBO INC
Contact Type:	GENERAL MANAGER
Contact Name:	JOE ROZZI
Address1:	1051 OCEAN AVE
Address2:	Not reported
City:	BROOKLYN
State:	NY
Zip Code:	11235
Country Code:	001
Phone:	(718) 645-1079
EMail:	Not reported
Fax Number:	Not reported
Modified By:	NTFREEMA
Date Last Modified:	2015-12-15

Tank Info:

Tank Number:	001
Tank Id:	213353
Material Code:	0022
Common Name of Substance:	Waste Oil/Used Oil

Equipment Records:

F06 - Pipe External Protection - Wrapped
G07 - Tank Secondary Containment - Excavation Liner
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
D01 - Pipe Type - Steel/Carbon Steel/Iron
I01 - Overfill - Float Vent Valve
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
L00 - Piping Leak Detection - None
C01 - Pipe Location - Aboveground
J00 - Dispenser - None

Tank Location:	Aboveground - contact with impervious barrier... Tank bottom rests on impervious barrier, allowing visual indication of leaks.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	04/19/1995
Capacity Gallons:	250
Tightness Test Method:	NN
Date Test:	Not reported

Next Test Date:	Not reported
Date Tank Closed:	02/01/2013
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	waste oil/used oil

Tank Number:	002
Tank Id:	242784
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
K01 - Spill Prevention - Catch Basin
A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I01 - Overfill - Float Vent Valve
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
C01 - Pipe Location - Aboveground
L00 - Piping Leak Detection - None
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	07/07/2011
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/01/2013
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	003
Tank Id:	242785
Material Code:	0021
Common Name of Substance:	Transmission Fluid

Equipment Records:

A00 - Tank Internal Protection - None
B01 - Tank External Protection - Painted/Asphalt Coating
I01 - Overfill - Float Vent Valve
C01 - Pipe Location - Aboveground
E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
D02 - Pipe Type - Galvanized Steel
G00 - Tank Secondary Containment - None
J02 - Dispenser - Suction Dispenser

	K01 - Spill Prevention - Catch Basin
	L00 - Piping Leak Detection - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - Removed
Pipe Model:	Not reported
Install Date:	08/20/2005
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	02/01/2013
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	transmission fluid

Tank Number:	004
Tank Id:	242786
Material Code:	0001
Common Name of Substance:	#2 Fuel Oil (On-Site Consumption)

Equipment Records:

	A00 - Tank Internal Protection - None
	B01 - Tank External Protection - Painted/Asphalt Coating
	E00 - Piping Secondary Containment - None
	H00 - Tank Leak Detection - None
	K01 - Spill Prevention - Catch Basin
	D02 - Pipe Type - Galvanized Steel
	F00 - Pipe External Protection - None
	L00 - Piping Leak Detection - None
	I05 - Overfill - Vent Whistle
	C03 - Pipe Location - Aboveground/Underground Combination
	G00 - Tank Secondary Containment - None
	J02 - Dispenser - Suction Dispenser
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	Closed - In Place
Pipe Model:	Not reported
Install Date:	Not reported
Capacity Gallons:	550
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	06/25/1972
Register:	True
Modified By:	MSBAPTIS
Last Modified:	04/14/2017
Material Name:	#2 fuel oil (on-site consumption)

Tank Number:	1001
Tank Id:	259989

Equipment Records:

	E00 - Piping Secondary Containment - None

H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2015
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	motor oil

Tank Number:	1002
Tank Id:	259990

Equipment Records:

E00 - Piping Secondary Containment - None
H00 - Tank Leak Detection - None
A00 - Tank Internal Protection - None
K00 - Spill Prevention - None
C01 - Pipe Location - Aboveground
I04 - Overfill - Product Level Gauge (A/G)
B00 - Tank External Protection - None
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
J01 - Dispenser - Pressurized Dispenser
G00 - Tank Secondary Containment - None
L00 - Piping Leak Detection - None

Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2015
Capacity Gallons:	275
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	motor oil

Tank Number:	1003
Tank Id:	259991
Equipment Records:	
	I04 - Overfill - Product Level Gauge (A/G) J00 - Dispenser - None A00 - Tank Internal Protection - None K00 - Spill Prevention - None B00 - Tank External Protection - None C00 - Pipe Location - No Piping F00 - Pipe External Protection - None E00 - Piping Secondary Containment - None H00 - Tank Leak Detection - None G12 - Tank Secondary Containment - Double-Walled (AG only) D00 - Pipe Type - No Piping L00 - Piping Leak Detection - None
Tank Location:	Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.
Tank Type:	Steel/Carbon Steel/Iron
Tank Status:	In Service
Pipe Model:	Not reported
Install Date:	09/01/2015
Capacity Gallons:	240
Tightness Test Method:	NN
Date Test:	Not reported
Next Test Date:	Not reported
Date Tank Closed:	Not reported
Register:	True
Modified By:	NTFREEMA
Last Modified:	04/14/2017
Material Name:	waste oil/used oil