Permit Evaluation Report 240298
Dovetail Energy, LLC
0829065027
February 09, 2022

ED_014244_00001055-00001

Ohio EPA, Division of Air Pollution Control

Permit Evaluation Report

Facility ID: 0829065027
Facility Name Dovetail Energy, LLC
Submitted: No

Report ID 240298
Report Type Permit Evaluation Report
Report Status Draft

Reporting Period 01/01/2021-12/31/2021
Due Date: **Feb 15, 2022**

1. Additional Information & Corrections

Please list below any additional information you need to communicate. At a minimum, identify if you have any EU(s) that were permanently shutdown, EU(s) that will not be installed or modified, or EU(s) not in operation during the reporting period. See the 'PER Form FAQ' document for an explanation and examples from the system's Reference Page.

The EU ID B001 and P001 where down at times during the 2021 reporting year due to System Improvements & upgrades. During that time the digester was also cleaned out and reseeded. This clean-out and reseed was put in place to rid the digester of all biosolids and to produce a better quality fertilizer with less odors. During the reseed there was no gas being produced there for the B001 and P001 where not needed in operation. None of this affected normal operations.

2. Detailed EU Information

The Emission Unit(s) listed below has been issued a PTIO(s). Complete the table below by identifying whether deviations or exceedances of operational restrictions(OR)/emission limitations(EL) and/or monitoring, record keeping or reporting (MRR) occured by selecting either Yes or No. If any of the date fields do not identify an actual date, you are required to update your Facility Profile for each applicable emissions unit(s).

			Dates			Deviations or Exceedances From:		
DAPC EU ID	DAPC EU Description	Permit Number: Effective Date	Completion of Initial Installation	Begin Installation/ Modification	Commence Operation after Installation or Latest Modification	OR/EL	MRR	Notes
B001	9.78 mmBtu/hr biogas engine	P0127783: 01/15/2020	Oct 01, 2013	Oct 01, 2013	Oct 01, 2013	No	No	
P001	750 kGal Digester with flare	P0124072: 04/09/2018	Oct 01, 2013	Oct 01, 2013	Oct 01, 2018	No	No	

3. Deviation, Exceedance, or Visible Emissions Detail

Additional information is required for each deviation or exceedance that prompted a 'yes' answer in the Detailed EU Information table above and for any visible emissions (VE) incident that occured during the reporting period. This information may be identified through either the following table or by attaching the information below. When attaching a document in lieu of using the table below, the document must meet the content requirements identified in the hard copy PER you received. Examples are available in the 'PER FAQs' document available from the system's Reference Page.

ED_014244_00001055-00002

Dev/Exc/VE ID	DAPC EU ID	Start Date	End Date	Duration	Description of Deviation or Exceedance and Probable Cause	Description of Corrective Actions. If none, describe why not
No records found						

4. Attachments

Attachment ID	Attachment Type	Description	Public Document	Trade Secret Document	Trade secret Justification	Event Date
No attachments found						

ED_014244_00001055-00003