Electron Hydro Intake Project

DATE Sept 26 2020

	Morning	Afternoon										
River Level	630											
Weather	Cloudy											
Precipitation												
Sample Location	1	2	3	4	5	6	7	8	9	10	11	12
Upstream Sample Point #1												
time	6.30 am	7.00	8 00	9.00	1.30							
NTU	50	45	45	40	38							
Turb Color	Semi clear	Semi clear	Semi clear	Semi clear	Semi clear							
pH	–	–	–	–	–							
Description of work performed												
Onstream Sample Point #2												
time	6.45	7.20	8 15	9.15	1:45							
NTU	50	45	40	37	38							
NTU Δ from #1	0	0	-5	-3	0							
Turb Color	Sem. clear	Semi clear	Sem. clear	Sem. clear	Semi clear							
pH	–	–	–	–	–							
pH Δ from #1	–	–	–	–	–							
Description of work performed												

Notes: work started @ 6:30 Am
· Crews in river continuing sheetpiling, excavating as needed
· Dewatering occurred throughout SHA
pump crew overnight to keep water levels down in work area.

Observed by (print): Corey Kleppe Signature:

In my signature I certify that this report is accurate and true as witnessed

EH00001553