STATUS: APPROVED

Return Main | Previous | Next

Insp Number:	2580	Insp Date:	2/6/2007
Insp Class:	Self Monitoring	Inspector:	KREBS, CHARLES
Insp Plant:	Gary Works		
Monitor Point:	No. 8 BF Casthouse Roof Monitor		
Duration:	2 Hr		

Mayella Reyes

SOURCE LAYOUTS

Edit SourceLayout

Acknowledgements

Name	Sign Off	Phone	Comments
MANGAHAS,MICHAEL		x 4116	
REYES,MAYELLA	Y	x7850	Comments Submit

Acknowledge Users..

CONDITIONS

<< 1 OF 1 >> Create New Condition | Save Conditions | Update Conditions | Delete

Date & Time:	2/6/2007 7:00:00 AM		
Background Color:	GRAY	Sky Conditions:	Party Cloudy
Wind Speed:	5	Wind Direction:	SOUTH WEST
Ambeint Temp:	0	Relative Humidity	60
Wet Bulb Temp:		Plume Type:	Attached

OBSERVATION POINTS

(Choose from Available Observation Points to Add to List; Selecet Obs. Point from list to enable Deletion)

Available Points:	None Selected
Minute:	0
Add	Delete

List of Selected Observation Points:

0	8BFC2 - E of slip and road under support structure for Sinter cross over

Method Limit	Limit Type and Color
20% over 6 Min	20.5% - IDEM

13% over 6 Min 13.5% - USS INTERNAL AUDIT

READINGS / OBSERVATIONS

Save Readings Add New Session View Exceedances

Session 0 Start Time: **Hour** 7 **Minute:** 0 **AM/PM** AM

Session 0 Comments:

Session	Time	:00	:15	:30	:45	Reading Comments (Minute)
0	7:00	0	0	0	0	
0	7:01	0	0	0	0	
0	7:02	0	0	0	0	
0	7:03	0	0	0	0	
0	7:04	0	0	0	0	
0	7:05	0	0	0	0	
0	7:06	0	0	0	0	
0	7:07	0	0	0	0	
0	7:08	0	0	0	0	
0	7:09	0	0	0	0	
0	7:10	0	0	0	0	
0	7:11	0	0	0	0	
0	7:12	0	0	0	0	
0	7:13	0	0	0	0	
0	7:14	0	0	0	0	
0	7:15	0	0	0	0	
0	7:16	0	0	0	0	
0	7:17	0	0	0	0	
0	7:18	0	0	0	0	
0	7:19	0	0	0	0	
0	7:20	0	0	0	0	
0	7:21	0	0	0	0	
0	7:22	0	0	0	0	
0	7:23	0	0	0	0	
0	7:24	0	0	0	0	
0	7:25	0	0	0	0	

0	7:26	0	0	0	0	
0	7:27	0	0	0	0	
0	7:28	0	0	0	0	
0	7:29	0	0	0	0	
0	7:30	0	0	0	0	
0	7:31	0	0	0	0	
0	7:32	0	0	0	0	
0	7:33	0	0	0	0	
0	7:34	0	0	0	0	
0	7:35	0	0	0	0	
0	7:36	0	0	0	0	
0	7:37	0	0	0	0	
0	7:38	0	0	0	0	
0	7:39	0	0	0	0	
0	7:40	0	0	0	0	
0	7:41	0	0	0	0	
0	7:42	0	0	0	0	
0	7:43	0	0	0	0	
0	7:44	0	0	0	0	
0	7:45	0	0	0	0	
0	7:46	0	0	0	0	
0	7:47	0	0	0	0	
0	7:48	0	0	0	0	
0	7:49	0	0	0	0	
0	7:50	0	0	0	0	
0	7:51	0	0	0	0	
0	7:52	0	0	0	0	
0	7:53	0	0	0	0	
0	7:54	0	0	0	0	
0	7:55	0	0	0	0	
0	7:56	0	0	0	0	
0	7:57	0	0	0	0	
0	7:58	0	0	0	0	
0	7:59	0	0	0	0	

0	[illegible]	0	0	0	0	
0	8:00	0	0	0	0	
0	8:01	0	0	0	0	
0	8:02	0	0	0	0	
0	8:03	0	0	0	0	
0	8:04	0	0	0	0	
0	8:05	0	0	0	0	
0	8:06	0	0	0	0	
0	8:07	0	0	0	0	
0	8:08	0	0	0	0	
0	8:09	0	0	0	0	
0	8:10	0	0	0	0	
0	8:11	0	0	0	0	
0	8:12	0	0	0	0	
0	8:13	0	0	0	0	
0	8:14	0	0	0	0	
0	8:15	0	0	0	0	
0	8:16	0	0	0	0	
0	8:17	0	0	0	0	
0	8:18	0	0	0	0	
0	8:19	0	0	0	0	
0	8:20	0	0	0	0	
0	8:21	0	0	0	0	
0	8:22	0	0	0	0	
0	8:23	0	0	0	0	
0	8:24	0	0	0	0	
0	8:25	0	0	0	0	
0	8:26	0	0	0	0	
0	8:27	0	0	0	0	
0	8:28	0	0	0	0	
0	8:29	0	0	0	0	
0	8:30	0	0	0	0	
0	8:31	0	0	0	0	
0	8:32	0	0	0	0	
0	[illegible]	0	0	0	0	

0	8:33	0	0	0	0	
0	8:34	0				
0	8:35					LT. BROWN
0	8:36					
0	8:37					25.4%
0	8:38					
0	8:39					BROWN/BLACK
0	8:40		50	20	15	
0	8:41	5	0	0	0	
0	8:42	0	0	0	0	
0	8:43	0	0	0	0	
0	8:44	0	0	0	0	
0	8:45	0	0	0	0	
0	8:46	0	0	0	0	
0	8:47	0	0	0	0	
0	8:48	0	0	0	0	
0	8:49	0	0	0	0	
0	8:50	0	0	0	0	
0	8:51	0	0	0	0	
0	8:52	0	0	0	0	
0	8:53	0	0	0	0	
0	8:54	0	0	0	0	
0	8:55	0	0	0	0	
0	8:56	0	0	0	0	
0	8:57	0	0	0	0	
0	8:58	0	0	0	0	
0	8:59	0	0	0	0	

STATUS: APPROVED

Return Main | Previous | Next

Insp Number:	2899	Insp Date:	3/14/2007
Insp Class:	Self Monitoring	Inspector:	MCCLURE, DANIEL
Insp Plant:	Gary Works		
Monitor Point:	No. 14 BF Casthouse Roof Monitor		
Duration:	2 Hr		

SOURCE LAYOUTS

Edit SourceLayout

Acknowledgements

Name	Sign Off	Phone	Comments
MANGAHAS,MICHAEL		x 4116	
REYES,MAYELLA	Y	x7850	Comments Submit

Acknowledge Users..

CONDITIONS

<< 1 OF 1 >> Create New Condition Save Conditions Update Conditions Delete

Date & Time:		3/14/2007 11:00:00 AM	
Background Color:	gray	Sky Conditions:	Party Cloudy
Wind Speed:	10	Wind Direction:	WEST
Ambeint Temp:	60	Relative Humidity	90
Wet Bulb Temp:		Plume Type:	Attached

OBSERVATION POINTS

(Choose from Available Observation Points to Add to List; Selecet Obs. Point from list to enable Deletion)

Available Points:	None Selected
Minute:	0
Add	Delete

List of Selected Observation Points:

0	14BFC1 - E of slip and road, 50 yds E of no. 45 slip ore boat tie down

Method Limit	Limit Type and Color
20% over 6 Min	20.5% - IDEM

13% over 6 Min 13.5% - USS INTERNAL AUDIT

READINGS / OBSERVATIONS

Save Readings Add New Session View Exceedances

Session 0 Start Time: **Hour** 11 **Minute:** 0 **AM/PM** AM

Session 0 Comments:

Session	Time	:00	:15	:30	:45	Reading Comments (Minute)
0	11:00	0	0	0	0	
0	11:01	0	0	0	0	
0	11:02	0	0	0	0	
0	11:03	0	0	0	0	
0	11:04	0	0	0	0	
0	11:05	0	0	0	0	
0	11:06	0	0	0	0	
0	11:07	0	0	0	0	
0	11:08	0	0	0	0	
0	11:09	0	0	0	0	
0	11:10	0	0	0	0	
0	11:11	0	0	0	0	
0	11:12	0	0	0	0	
0	11:13	0	0	0	0	
0	11:14	0	0	0	0	
0	11:15	0	0	0	0	
0	11:16	0	0	0	0	
0	11:17	0	0	0	0	
0	11:18	0	0	0	0	
0	11:19	0	0	0	0	
0	11:20	0	0	0	0	
0	11:21	0	0	0	0	
0	11:22	0	0	0	0	
0	11:23	0	0	0	0	
0	11:24	0	0	0	0	
0	11:25	0	0	0	0	