To: Sharp-Dahl, Julie[jsharp-dahl@bristol-companies.com]; KHanson@ldftribe.com[KHanson@ldftribe.com]
From: Egan, Robert
Sent: Mon 12/29/2014 5:55:56 PM
Subject: RE: Tower Standard tap water data

Julie,

Can you coordinate the sample that had the xylene hits to an address?

Thanks.

Bob Egan

Corrective Action Manager

Underground Storage Tanks Section

RCRA Branch

(312) 886-6212

(312) 692-2911 (fax)

From: Sharp-Dahl, Julie [mailto:jsharp-dahl@bristol-companies.com]
Sent: Monday, December 29, 2014 10:50 AM
To: KHanson@ldftribe.com; Egan, Robert
Subject: Tower Standard tap water data

Hi Kristen,

I received your call regarding the analytical results for the three tap water samples you submitted for us. Attached are the analytical results. The "J" flag adjacent a results means that the result is an estimated value and the "B" means the result may be elevated due to method blank contamination.

Please email or call if you have questions. Thank you again Kristen for your help.

I hope you have a Happy New Year!

Julie Sharp-Dahl
Senior Project Manager
Bristol Environmental Remediation Services, LLC
111 W. 16th Avenue, Third Floor
Anchorage, AK 99501-5109
Phone : (907) 743-9394
FAX : (907) 563-6713
jsharp-dahl@bristol-companies.com
http://www.bristol-companies.com/

CONFIDENTIAL NOTICE: This document is for the sole purpose of the intended recipient(s) and may contain confidential and privileged information. Any unauthorized review, use, disclosure, or distribution is prohibited. If you are not the intended recipient, please contact the sender and destroy all copies of the original document.

--