Location: 17 SNOW VISTA ARROYO AT SAGE RD

DATE 11/22/2010 **TIME** 2:45 **WEATHER** Cloudy

SUSPECTED SOURCE na

EST. FIOW, CFS 0 **1 cfs =449 gpm**

SUSPECTED PROBLEM TYPE na

AIR TEMP,° 63 **PH:**

WATER TEMP,°F **APPEARANCE:**

DISS OXYGEN, MG/L: **OBSERV GROSS POLLUT:**

CONDUCTANCE, µMHOS/CM **INSPECTOR** SK

FIELD NOTES no flow