EPA United States Environmental Protection Agency

Region 6 Compliance Assurance and Enforcement Division

INSPECTION REPORT

Inspection Date(s):	January 3, 2017		
Media:	Brine		
Regulatory Program(s)	Underground Injection Control - Brine		
Company Name:	No-Name Osage County (SE 11-25-11)		
Facility Name:	Unknown (Bird Creek)		
Facility Physical Location:	/4, Sec. , T , R		
(city, state, zip code)	Pawhuska, Pawhuska, Oklahoma		
Mailing Address:	Unknown		
(city, state, zip code)	Unknown		
County/Parish:	Osage		
Facility Contact	N/A		N/A
	N/A		
FRS Number:	N/A		
Identification/Permit Number:	N/A		
Media Number:	N/A		
NAICS:	21111		
SIC:	1311		
Facility Representatives:	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Inspectors:	K.W. Sanborn	6EN-WR	918-557-1615
	N/A	N/A	N/A
	N/A	N/A	N/A
State Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
Other Inspector(s):	N/A	N/A	N/A
	N/A	N/A	N/A
EPA Lead Inspector Signature/Date	Kent Sanborn Digitally signed by Kent Sanborn DN: cn=Kent Sanborn, o=EPA, ou, email=sanborn.kent@epa.gov, c=US Date: 2017.02.14 14:57:39 -06'00'		
	Kent Sanborn		Date
Supervisor Signature/Date	WILLIE LANE Digitally signed by WILLIE LANE Date: 2017.02.14 16:00:06 -06'00'		
	Willie Lane Jr., Chief, Water Resources Section(6EN-WR)		Date

Section I - INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the No-Name Osage County (SE 11-25-11) oil production facility located in the Latitude: 36.83216, Longitude: -96.498037 near Pawhuska, on January 3, 2017. No representative of No-Name Osage County (SE 11-25-11) was present for the inspection. The inspection was conducted by authority of the Clean Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

A creek survey of Bird Creek was conducted. The brine discharge site was located on a ranch property owned by the Bass Brothers north of Pawhuska.

Section II - OBSERVATIONS

During the creek survey of Bird Creek, a Total Soluble Salts (TSS) measurement was taken with a calibrated YSI 30 conductivity meter. The TSS was 4,900 parts-per-million (ppm) at latitude 36.817297N and longitude -96.495558W. A TSS readings between 29,000ppm and 37,000 ppm was taken at the bridge near the point of entry to Bird Creek. I observed no flow and there had been no rain recently at the time of the inspection.

Section III - AREAS OF CONCERN

At the time of the inspection, brine was still present in Bird Creek. The TSS concentrations varied by location and distance from the apparent discharge point of entry into Bird Creek.

Section IV - FOLLOW UP

Conduct a follow up inspection in approximately one month.

Section V - LIST OF APPENDICES

There are no attachments to this report.